

POWER AUTHORITY OF THE STATE OF NEW YORK
INDIAN POINT NO. 3 NUCLEAR POWER PLANT

P. O. BOX 215 BUCHANAN, N. Y. 10511

TELEPHONE: 914-739-8200



March 1, 1979

IP-JJK-4236

REGULATORY DOCKET FILE COPY


Mr. Boyce H. Grier, Director
Office of Inspection and Enforcement
Region 1
U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406

Dear Mr. Grier:

I have enclosed a copy of the Semiannual Report of Radioactivity in Solid Wastes and Releases of Radioactive Materials in Liquid and Gaseous Effluents for Indian Point 3 as required by section 5.6.1.C of the Environmental Technical Specifications of Operating License DPR-64 for Indian Point 3 Docket No. 50-286. The enclosed report covers the period July 1 through December 31, 1978 for Indian Point 3 and includes those releases from the Indian Point 1 and 2 liquid waste processing system which resulted from processing liquid waste from Indian Point 3.

During preparation of this report it was discovered that an error was made in reporting the second quarter 1978 tritium gaseous effluent data in the last semiannual report. The value for Table 1A in D.1 tritium "Total Release" was 2.14 E-4 and should be 2.37 E+0. The value for Table 1A in D2 "Average Release Rate for Period" was 2.73 E-5 and should be 3.02 E-1. This does not change any results reported in Section E., "Radiological Impact on Man".

Sincerely,


J. P. Bayne
Resident Manager

JJK:ah

cc: Mr. Harold Denton, Director
Office of Nuclear Reactor Regulation
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Dr. Ernst Volgenau (30 copies)
Office of Inspection and Enforcement
c/o Distribution Services Branch, DDC, ADM
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

7903060419

50-286

A007
E3
30/30
R