William J. Cahill, Vice President

Consolidated Edison Company of New York, Inc. REGULATORY DOCKET FILE COPY 4 Irving Place, New York, N Y 10003 Telephone (212) 460-3819

July 19, 1979

RE: Indian Point Unit Nos. 1,2&3 Docket Nos. 50-3, 50-247, 50-286

Mr. Boyce H. Grier, Director Office of Inspection and Enforcement Region 1 U. S. Nuclear Regulatory Commission 631 Park Avenue King of Prussia, Pennsylvania 19406

Dear Mr. Grier

In accordance with the Environmental Technical Specification Requirements (ETSR) a new milk sampling location was chosen using data from the milch animal survey conducted this year and was chosen to be as close to the plant as possible based on the availability of milch animals in the area. The new site is Hilltop Hanover Farm.

This site replaced Guard Hill Farm as a sampling site and is located outside the 15 mrem/yr isodose line. Guard Hill Farm ceased commercial operation during Januray 1979. A January 1979 sample was obtained. The Office of Inspection and Enforcement, Region 1, was notified of the closing of Guard Hill Farm by telecommunication on February 6, 1979 which was followed up by a 30 day report dated March 6, 1979.

Monthly milk sampling at Hilltop-Hanover Farm was initiated in June 1979.

This change will be incorporated into a future revision of the Technical Specifications.

Very truly yours

ililliam alul

(1004 510 7908010 343

Copies: Mr. John G. Davis, Acting Director Office of Inspection and Enforcement c/o Distribution Services Branch, DDC, ADM U.S. Nuclear Regulatory Commission Washington, D.C. 20555

. ? .

Mr. Harold Denton, Director Office of Nuclear Reactor Regulation U.S. Nuclear Regulatory Commission Washington, D.C. 20555

Mr. George T. Berry Executive Director Power Authority of the State of New York 10 Columbus Circle New York, N.Y. 10019