


William J. Cahill, Jr.
Vice President

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, N Y 10003
Telephone (212) 460-3819




November 1976

Regulatory Docket File

Indian Point Unit Nos. 1, 2, & 3
& 50-286

Mr James P. O'Reilly
Director of Region I
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406



Dear Mr. O'Reilly

Pursuant to Appendix B of Unit Nos. 1, 2 & 3 Technical Specifications with respect to the operation of our Unit Nos. 1, 2 & 3, a tabulation of daily record of fish collections at Indian Point Nos. 2 & 3 for the month of October is enclosed. A daily species breakdown and total daily weights are also enclosed. For Unit No. 2 the following corrective actions were taken on the dates indicated to reduce impingement numbers:

<u>Date</u>	<u>Total</u>	<u>Corrective Action</u>
10/13	7471	Screens properly bottomed
10/17	8896	1 circulator shutdown
10/18	5609	1 circulator shutdown
10/23	10529	2 circulators shutdown
10/25	6228	Screens properly bottomed
10/26	23112	1 circulator shutdown
10/27	11760	1 circulator shutdown

The following were the corrective actions taken at Unit No. 3 during the month of October.

<u>Date</u>	<u>Total</u>	<u>Corrective Action</u>
10/13	47887	1 circulator shutdown
10/14	5159	1 circulator shutdown
10/15	6859	1 circulator shutdown
10/21	6920	1 circulator shutdown
10/22	9328	1 circulator shutdown
10/23	5049	2 circulators shutdown
10/24	3923	Reduced flow (60%) on two circulators

811110223 761116
PDR ADOCK 05000247
R PDR

11900

The circulators which were shutdown are those whose intake screens had the highest percentage of impinged fish.

Very truly yours



William J. Cahill, Jr.
Vice President

enc.

cc: Mr. Ben C. Rusche
James P. Corcoran, Esq.
Sarah Chasis, Esq.
Michael Curley, Esq.
Nicholas A. Robinson, Esq.
Mr. George T. Berry