CONSOLIDATED EDISON COMPANY OF NEW YORK, INC. 4 IRVING PLACE, NEW YORK, N.Y. 10003

AND

NEW YORK POWER AUTHORITY 123 MAIN STREET, WHITE PLAINS, N.Y. 10601

July 12, 1984

Mr. Harold R. Denton, Director Office of Nuclear Reactor Regulation U.S. Nuclear Regulatory Commission Washington, D.C. 20555

Subject: Indian Point Unit 2

Docket No. 50-247

Indian Point Unit 3 Docket No. 50-286

Amendment 2 to the Indian Point Probabilistic Safety Study

Dear Mr. Denton:

Enclosed are fifty copies, numbered 1 through 50, of an erratum to Amendment 2 of the Indian Point Probabalistic Safety Study issued April 10, 1984. In this erratum a correction has been made to Figure 7.2-10A-3 in the Section on "Unit 2 Additional Seismic Analysis".

Should you or your staff have any questions regarding this letter or its enclosures, please contact us.

ive Vice President

York Power Authority

Very/truly yours,

John D. O'Too.

Vice President

Consolidated Edison Company

of New York, Inc.

Enclosures (as stated)

Figure 7.2-10A-3. Release Frequency from Seismic Events, Indian Point 2 (After Modification to the Control Building)