

Murray Selman  
Vice President

Consolidated Edison Company of New York, Inc.  
Indian Point Station  
Broadway & Bleakley Avenue  
Buchanan, NY 10511  
Telephone (914) 737-8116

July 14, 1987

Re: Indian Point Unit No. 2  
Docket No. 50-247

U.S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Washington, DC 20555

SUBJECT: Inservice Testing and Inspection Program - Technical  
Specifications For Indian Point Unit No. 2

Dear Sir:

By letter dated July 18, 1986, Consolidated Edison Company of New York, Inc. ("Con Edison") submitted Revision 1 of the "Inservice Testing Program Summary for the Interval July 1, 1984 through June 30, 1994. Attachment A to that letter contained a revised Technical Specification change request that would replace the existing Inservice Inspection Program contained in Section 4.2 of the Technical Specifications, in its entirety, with a commitment to an Inservice Inspection and Testing Program and periodic updating, consistent with 10CFR50.55a. That revision superseded our previously proposed Technical Specification change requests dated May 5, 1977 and February 16, 1984.

By letter dated May 7, 1987, NRC staff requested that Con Edison resubmit the Technical Specification change request such that it provides for compliance with 10CFR50.55a(g) "except where specific relief has been granted." In response to that letter, we are submitting the attached replacement page to the first page of Con Edison's July 18, 1986 Technical Specification change request submittal, Attachment A. The Safety Assessment and the No Significant Hazards Considerations submitted previously in the July 18, 1986 submittal remain valid for this page revision.

If you or your staff have any questions, please contact us.

Very truly yours,

*Murray Selman*

8707220226 870714  
PDR ADDCK 05000247  
P PDR

A097  
10