

John D. O'Toole
Assistant Vice President

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, N Y 10003
Telephone (212) 460-2533

Letter No. 81-37
February 26, 1981

Re: Indian Point Unit No. 2
Docket No. 50-247

Director of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

ATTN: Mr. Darrell G. Eisenhut, Director
Division of Licensing

Dear Mr. Eisenhut:

By letter dated October 31, 1980, you requested that all licensees provide confirmation that the implementation dates indicated in Enclosure 1 of NUREG-0737 "Clarification of TMI Action Plan Requirements" will be met. Where the dates could not be met, you requested a proposed revised date, justification for the delay, and any planned compensating safety actions during the interim.

As you are aware, Indian Point Unit No. 2 has been shutdown since October 17, 1980 and will remain so until April 15, 1981 for refueling, maintenance, inservice inspection and testing, fan cooler heat exchanger replacement and modifications resulting from our investigation of the recent containment flooding incident. In addition, we are implementing plant modifications for various NRC regulatory requirements including asymmetric RCS loading, environmental qualification, fire protection and TMI-2 lessons learned. Accordingly, any Task Item requiring a January 1, 1981 implementation is planned for completion prior to returning the unit to service and is, therefore, considered to be in compliance with the implementation schedule of Enclosure 1 to NUREG-0737.

1981 FEB 30 AM 9 55

REGISTRATION
DIVISION

A046
S
1/1

8103030

722


P

Attachment 1 to this letter provides our response to NUREG-0737. This Attachment addresses all Task Items applicable to Indian Point Unit No. 2 with particular emphasis on the items requiring implementation by January 1, 1981. Any NUREG-0737 Task Item for which we are proposing an alternative implementation schedule is identified in Attachment 1 by an asterisk (*). For these items, alternative implementation dates, justification for the delays, and any compensating actions are addressed in the individual Task Item responses.

With regard to your July 2, 1980 letter to all licensees requesting proposed technical specifications for certain TMI lessons learned items, please be advised that such a proposal will also be submitted to the Commission prior to returning the unit to service from the present outage.

In accordance with your October 31, 1980 letter, this submittal is being made pursuant to 10 CFR 50.54(f). Should you or your staff have any questions, please contact us.

Very truly yours,



John D. O'Toole
Assistant Vice President

attach.

Subscribed and sworn to
before me this 26th day
February, 1981.


Notary Public

ROBERT P. SELYA
Notary Public, State of New York
No. 8917645
Qualified in New York County
Commission Expires March 30, 1982