

John D. O'Toole  
Vice President

4/28

Consolidated Edison Company of New York, Inc.  
4 Irving Place, New York, NY 10003  
Telephone (212) 460-2533

Letter No. 81-80

April 24, 1981

Re: Indian Point Unit No. 2  
Docket No. 50-247

Director of Nuclear Reactor Regulation  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

ATTN: Mr. Steven A. Varga, Chief  
Operating Reactors Branch No. 1  
Division of Licensing

Dear Mr. Varga:

This letter supplements our letter dated March 13, 1981, regarding the results of our steam generator inspection program. That earlier program was confined to the hot side of the steam generators, as were all previous inspection programs.

As directed by you, in a conference call on April 17, 1981, we have completed an additional program of inspections of specified tubes in all four steam generators on the cold side of the steam generators. Attachment 1 summarizes the results of our additional inspections.

Should you or your staff have any questions, please contact us.

Very truly yours,

*John D. O'Toole*

cc: Mr. T. Rebelowski, Resident Inspector  
U. S. Nuclear Regulatory Commission  
P. O. Box 38  
Buchanan, N. Y. 10511

Asol  
5/11

8104290 525

P