

John D. O'Toole
Vice President

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, NY 10003
Telephone (212) 460-2533

February 24, 1982

Re: Indian Point Unit No. 2
Docket No. 50-247

Director of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

ATTN: Mr. Steven A. Varga, Chief
Operating Reactors Branch No. 1
Division of Licensing



Dear Mr. Varga:

This letter is in response to your letter dated January 21, 1982 requesting supplemental information in order to complete your generic review of IE Bulletin 80-04 "PWR Main Steam Line Break with Continued Feedwater Addition".

In response to item A.1 of the enclosure to your letter, we have begun an evaluation to determine the potential for a single active failure in the main feedwater system which could cause the greatest feedwater flow to the affected steam generator during a main steam line break accident. We expect to complete this evaluation by April 1, 1982, after which a schedule for responding to the remaining issues contained in your January 21, 1982 letter will be provided.

Very truly yours,

A handwritten signature in cursive script that reads "John D. O'Toole".

Aool
S.10

8203080346 820224
PDR ADOCK 05000247
Q PDR