John D. OToole ce.President

Consolidated Edison Company of New York, Inc. 4 Irving Place, New York, NY 10003 Telephone (212) 460-2533

February 17, 1983

Indian Point Unit No. 2 Docket No. 50-247

Director of Nuclear Reactor Regulation U. S. Nuclear Regulatory Commission Washington, D. C. 20555

> Mr. Steven A. Varga, Chief Operating Reactors Branch No. 1 Division of Licensing

Dear Mr. Varga:

ATTN:

As required by Indian Point 2 Technical Specification 4.13, we conducted a steam generator inspection program during the recently completed Cycle 5/6 refueling/maintenance outage. This inspection program was outlined in my letter to you, dated August 18, 1982 and in discussions with your The results of this program and supplemental inspections are staff. submitted as attachments to this letter.

Re :

Previous submittals of this type required NRC approval before plant start-up in the form of a license amendment and payment of a filing fee. Based on the Technical Specifications as revised by Amendment No. 81 this procedure no longer applies. In accordance with the present Technical Specifications, we will continue to submit our steam generator inspection program 60 days before the beginning of an inspection outage and will report the results of the inspection program 45 days after the completion of the inspection outage. Since these reports are now being submitted in compliance with an existing technical specification, it is our interpretation that filing fees are no longer appropriate.

Should you or your staff have any questions please contact us.

Verty trainy When J. Invole A001 ./40 Recol vertout OR:g.~...

attach.

