

John D. O'Toole
Vice President

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, NY 10003
Telephone (212) 460-2533

December 24, 1984

Re: Indian Point Unit No. 2
Docket No. 50-247

Director of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

ATTN: Mr. Steven A. Varga, Chief
Operating Reactors Branch No. 1
Division of Licensing

Dear Mr. Varga:

On December 21 and 22, 1984, discussions were held among members of our staffs regarding the Indian Point Unit No. 2 control room habitability analyses. Those analyses were submitted by Consolidated Edison on May 12, 1981 and September 4, 1981 in response to Item III.D.3.4 of NUREG-0737, and were approved by the NRC Staff in their SER issued on January 27, 1982.

We understand that you will be requesting additional information on certain aspects of Con Edison's analyses. Since variations in certain input parameters can affect the dose calculations in these analyses, at your request we have reviewed our existing emergency plan procedures with respect to radiological control of the central control room. Those procedures specifically address the use of potassium iodide and self contained breathing apparatus by the central control room personnel when appropriate. These items are on hand in the central control room.

Very truly yours,



cc: Senior Resident Inspector
U. S. Nuclear Regulatory Commission
P.O. Box 38
Buchanan, New York 10511

A046
1/0

8412280167 841224
PDR ADDCK 05000247
F PDR