

John D. O'Toole
Vice President

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, NY 10003
Telephone (212) 460-2533

January 15, 1985

Re: Indian Point Unit No. 2
Docket No. 50-247

Director of Nuclear Reactor Regulation
U.S. Nuclear Regulatory Commission
Washington, D. C. 20555

ATTN: Mr. Steven A. Varga, Chief
Operating Reactors Branch No. 1
Division of Operating Reactors

Dear Mr. Varga:

In accordance with Section V.B of Appendix J to 10 CFR Part 50, transmitted herewith is a summary technical report for Indian Point Unit No. 2 entitled, "Reactor Containment Building Integrated Leak Rate Test." This report contains the results of the Type A containment leakage rate test performed during the unit's recently completed sixth refueling outage and also the Type B and C containment local leakage rate tests performed during the unit's fourth, fifth and sixth refueling outages. As demonstrated in the report, the Indian Point Unit No. 2 containment leakage rate satisfies the requirements of Appendix J to 10 CFR Part 50 and the Technical Specifications.

Should you or your staff have any questions, please contact us.

Very truly yours,



encl.

cc: Mr. D. J. Vito, Reactor Engineer
Region I
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pa. 19406

Senior Resident Inspector
U. S. Nuclear Regulatory Commission
P. O. Box 38
Buchanan, New York 10511

8501240092 850115
PDR ADDCK 05000247
PDR
P

A017
1/1