

John D. O'Toole
Vice President

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, NY 10003
Telephone (212) 460-2533

February 18, 1986

Re: Indian Point Unit No. 2
Docket No. 50-247

Mr. Steven A. Varga, Director
PWR Project Directorate No. 3
Division of PWR Licensing - A
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Dear Mr. Varga:


The Attachment to this letter confirms the information provided to you during telephone discussions with members of my staff on January 31, February 3, and February 13, 1986 and is also in response to your letter of February 6, 1986. Although your February 6 letter was quite broadly phrased, based upon the telephone discussions, we understand that you are requesting our analysis of alternative measures and systems, which could be called upon in the event of the unavailability of the Diesel Generator Building, the Control Building and the Condensate Storage Tank due to damage caused by high winds. As noted in the Attachment our current assessment of high wind risks for Indian Point Unit 2 (IP-2) is contained in Amendment 2 of the IPPSS submitted to NRC in April, 1984.

If you or your staff have any further questions do not hesitate to call us.

Very truly yours,



cc: Senior Resident Inspector
U. S. Nuclear Regulatory Commission
P. O. Box 38
Buchanan, New York 10511



Aool
1/1