

John D. O'Toole  
Vice President

Consolidated Edison Company of New York, Inc.  
4 Irving Place, New York, NY 10003  
Telephone (212) 460-2533

July 31, 1986

Re: Indian Point Unit No. 2  
Docket No. 50-247


Mr. Hugh L. Thompson, Jr., Director  
Division of PWR Licensing - A  
Office of Nuclear Reactor Regulation  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Dear Mr. Thompson:

Attachment 1 contains Con Edison's Safety Analysis Report (SAR) for the Safety Assessment System/Safety Parameter Display System (SAS/SPDS). This fulfills our commitment contained in our January 24, 1986 submittal regarding the SAR revision for SAS/SPDS. Attachment 2 contains responses to your staff's request for information of April 3, 1986 regarding the SAS/SPDS. This SAR for the SAS/SPDS supersedes the SAR contained in our August 15, 1984 submittal.

If you have any questions, do not hesitate to call us.

Very truly yours,



cc: Senior Resident Inspector  
U. S. Nuclear Regulatory Commission  
P. O. Box 38  
Buchanan, New York 10511

8608040247 860731  
PDR ADDCK 05000247  
P PDR

A001  
1/1