

Murray Selman
Vice President

Consolidated Edison Company of New York, Inc.
Indian Point Station
Broadway & Bleakley Avenue
Buchanan, NY 10511
Telephone (914) 737-8116

December 29, 1986

Re: Indian Point Unit No. 2
Docket No. 50-247


Dr. Thomas E. Murley
Regional Administrator - Region I
U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406

Dear Dr. Murley:

As required by 10 CFR 50.54, we are submitting as an attachment to this letter a description of our current Quality Assurance (QA) program. This attachment, entitled Quality Assurance Program - Revision 4, supersedes Revision 3 which was submitted to you on December 20, 1985.

Revision 4 incorporates recent corporate organizational and authority changes, requirements for environmental qualification to meet the intent of 10 CFR 50.49 and greater details in the audit program to reflect technical specifications requirements.

Very truly yours,



Attachment

cc: Mr. James M. Taylor, Director
Office of Inspection & Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Office of Senior Resident Inspector
U.S. Nuclear Regulatory Commission
P.O. Box 38
Buchanan, NY 10511

8701130327 861229
PDR ADDCK 05000247
PDR

Q 001
11

RECEIVED-REGION 1
1987 JAN -5 PM 3:56