NRC FORM 591M PART 1 (10-2003) 10 CFR 2.201			U.S. NUCLEAR REGU	LATORY COMMISSI
SAFETY INSP	ECTION REPORT	AND COMPLIA	NCE INSPECTION	
Department of the Army Coane Army; Crune Indiana and Bluegrass Army Depot; Richmond, KY REPORT NUMBER(S) 2010-001		AND COMPLIANCE INSPECTION 2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region III 2443 Warrenville Road Suite 210 Lisle, Illinois 60532-4351		
3. DOCKET NUMBER(S) ○ 🕻 O - O 8767	4. LICENSEE NUM Suc-138	BER(S)	5. DATE(S) OF I	NSPECTION
LICENSEE: The inspection was an examination of to compliance with the Nuclear Regulat The inspection consisted of selective exand observations by the inspector. The 1. Based on the inspection findings, no 2. Previous violation(s) closed. 3. The violation(s), specifically described identified, non-repetitive, and corrective a 1600, to exercise discretion, were satisfied.	xaminations of proces inspection findings a violations were identified. d to you by the inspector a action was or is being take ed.	dures and region dures and region dures and represented as follows: as non-cited violations, and the remaining	entative records, intervie	diation safety and ns of your license was with personn they were self- ent Policy, NUREG-
4. During this inspection certain of your a cited. This form is a NOTICE OF VIOLATI (Violations and Corrective Actions)	or, miorinay be subjec	i to posting in accorda	Ince with 10 CFR 19.11.	ements and are being
I hereby state that, within 30 days, the actions desorrective actions is made in accordance with the redate when full compliance will be achieved). I undate when full compliance will be achieved). I undate when full compliance will be achieved. I undate will be achieved.	s Statement of Correcti scribed by me to the inspe equirements of 10 CFR 2.2 derstand that no further wi ed Name	ector will be taken to co 201 (corrective steps a ritten response to NRC	orrect the violations identified.	This statement of s which will be taken, ifically requested. Date
RC INSPECTOR Michael La	F	Mald M	91	1/27/10

82B

NRC FORM 591M PART 3			I.S. NUCLEAR REGULATORY			
(10-2003) 10 CFR 2,201		Information C	OMMISSION			
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION						
LICENSEE Department of the Army		2. NRC/REGIONAL OFFICE				
REPORT 2010-001 NUMBER(S)		Region III 2443 Warrenville Road, Suite 210 Lisle, IL 60532				
3. DOCKET NUMBER(S)	4. LICENSE NUMBER(S)		5 DATE(S) OF INSPECTION			
040-08767 SUC-1380 5. INSPECTION PROCEDURES USED 7. INSPECTION FOCUS A		1/20-21/10 thru 1/27/10				
87126	03.01-03.07					
		ECTION INFORMATION				
1 PROGRAM CODE(S) 2 PRIORITY 5	3. LICENSEE CONTACT Kelly Crooks RSO		4. TELEPHONE NUMBER 309-782-2969			
Main Office Inspection		Next Inspection Date	e: 1/2015			
X Field Office Crane Army; Crane	e, Indiana and Blueg	rass Army Depot; Richr	nond, KY			
Temporary Job Site Inspection						
The licensee is authorized to possess, store, receive and transfer depleted uranium at a number of facilities throughout the United States. The licensee transfers depleted uranium throughout the United States and also makes transfers and receives material to and from outside the United States. The licensee is authorized for the disassembly of depleted uranium components but is not performing that activity under this license. Decommissioning activities are authorized at the Lake City Army Ammunition plant in Independence, Missouri – that portion of the license was not inspected as other portions of the NRC inspection program are dealing with that issue. Observations and Findings The inspector went to the two authorized field offices noted above. The inspector conducted interviews with licensee staff and identified that adequate knowledge was possessed to ensure safe storage and transfer of licensed material. The inspector performed independent radiation measurements and did not identify any abnormal radiation levels. The inspector reviewed documentation associated with inventories, audits and dosimetry; no abnormal issues were identified. The inspector visited a number of storage magazine buildings at each field office and noted licensed material was appropriately stored, secured and posted. The inspection was extended to 1/27/10 allow the licensee time to document and provide NRC a total inventory of licensed material under the license. An exit meeting was conducted on 1/27/10.						

NRC FORM 591M PART 3 (10-2003)

In Bloom