

APPENDIX A

NOTICE OF VIOLATION

Consolidated Edison Company of New York, Inc.  
Indian Point Station, Unit 2

Docket No. 50-247  
License No. DRP-26

As a result of the inspection conducted on April 9-13, 1990, and in accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C, the following violation was identified:

10 CFR 50.49, Section (e)(1), requires that "time-dependent temperature and pressure at the location of the electric equipment important to safety must be established for the most severe design basis accident during or following which this equipment is required to remain functional."

Contrary to the above, as of April 13, 1990, the maximum temperature at the location of the Residual Heat Removal Pumps was determined to be 202°F, instead of 150°F, as stated in the FSAR and used for qualification of these pump motors.

This is a Severity Level IV violation. (Supplement I)

Pursuant to the provisions of 10 CFR 2.201, Consolidated Edison Company of New York, Inc. is hereby required to submit to this office within thirty days of the date of the letter which transmitted this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending this response time.

OFFICIAL RECORD COPY

ND IP2 - 0003.0.0  
06/14/90

9006280384 900628  
PDR ADDCK 05000247  
PTC