

Carl L. Newman
Vice President


Regulatory Docket File

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, N. Y. 10003
Telephone (212) 460-5133

August 13, 1974

Re Indian Point Unit No. 1
AEC Docket No. 50-3
AO 4-1-24

Mr. James P. O'Reilly, Director
Directorate of Regulatory Operations
Region I
U. S. Atomic Energy Commission
631 Park Avenue
King of Prussia, Penn. 19406



Dear Mr. O'Reilly

In accordance with the Technical Specifications of Facility Operating License No. DPR-5, we wish to inform you of an Abnormal Occurrence (AO 4-1-24), which was identified and reported to Mr. Anthony Fasano of your office on August 12, 1974.

The occurrence is the type defined by Technical Specification 6.3.A.1.b.(4) and relates to a condition which could have prevented the Main Steam Stop Valve for Steam Generator No. 13 from performing its intended safety function.

The condition was noted during a startup of Unit No. 1 on August 11, 1974 when it was found that the subject motor-operated valve could not be opened remotely from the Central Control Room. Investigation revealed that power supply fuses had blown and the drive motor windings were grounded. The motor was replaced and the valve was then tested satisfactorily. Further investigation to determine the specific cause of the electrical fault is continuing.

Since the valve had been successfully operated electrically approximately one hour prior to when the problem was noted and since the fault apparently developed with the valve in the closed, safe, position, the safety implications of this occurrence are not considered significant.

A follow-up report on this occurrence will be submitted within ten days.

Very truly yours

Carl L. Newman

Carl L. Newman
Vice President


mk

8162

8103060713

William J. Cahill, Jr.
Vice President

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, N.Y. 10003
Telephone (212) 460-3819



July 29, 1974

Re Indian Point Unit No. 1
AEC Docket No. 50-3
A.O. 4-1-23

Mr. James P. O'Reilly, Director
Directorate of Regulatory Operations
Region I
U. S. Atomic Energy Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406



Dear Mr. O'Reilly

In accordance with the Technical Specifications of Facility Operating License No. DPR-5, the enclosed 10-day report of an Abnormal Occurrence is submitted.

Very truly yours

William J. Cahill, Jr.
William J. Cahill, Jr.
Vice President

lp

REGULATORY DOCKET FILE COPY

7991