

Stephen E. Quinn  
Vice President

Consolidated Edison Company of New York, Inc.  
Indian Point Station  
Broadway & Bleakley Avenue  
Buchanan, NY 10511  
Telephone (914) 734-5340

January 31, 1995

Re: Indian Point Unit No. 2  
Docket No. 50-247


Document Control Desk  
US Nuclear Regulatory Commission  
Mail Station P1-137  
Washington, DC 20555

SUBJECT: Proposed Amendment to Technical Specifications  
Regarding Steam Generator Tube Slewing and  
Acceptance Criteria

Consolidated Edison Company of New York, Inc. (Con Edison) proposed an amendment to the Indian Point Unit No. 2 Technical Specifications by letter dated April 13, 1994, which would permit steam generator tube slewing. Additionally, a new tube acceptance criteria, F\*, was proposed. At this time, Con Edison requests that the portion of the amendment request pertaining to steam generator tube slewing be separated from the original request in order to allow additional review of current slewing technical issues. Proposed Technical Specification pages which support this separation, are attached.

Should you have any questions regarding this matter, please contact Mr. Charles W. Jackson, Manager, Nuclear Safety and Licensing.

Very truly yours,



Attachment

070130

9502070360 950131  
PDR ADOCK 05000247  
P PDR

ADD 11

cc: Mr. Thomas T. Martin  
Regional Administrator - Region I  
US Nuclear Regulatory Commission  
475 Allendale Road  
King of Prussia, PA 19406

Mr. Francis J. Williams Jr., Project Manager  
Project Directorate I-1  
Division of Reactor Projects I/II  
US Nuclear Regulatory Commission  
Mail Stop 14B-2  
Washington, DC 20555

Senior Resident Inspector  
US Nuclear Regulatory Commission  
PO Box 38  
Buchanan, NY 10511

Mayor, Village of Buchanan  
236 Tate Avenue  
Buchanan, NY 10511

Ms. Donna Ross  
Division of Policy Analysis and Planning  
New York State Energy Office  
Agency Building 2, Empire State Building  
Albany, NY 12223

ATTACHMENT

CONSOLIDATED EDISON COMPANY OF NEW YORK, INC.  
INDIAN POINT UNIT NO. 2  
DOCKET NO. 50-247  
JANUARY, 1995