

CENTRAL FILES

POWER AUTHORITY OF THE STATE OF NEW YORK
INDIAN POINT NO. 3 NUCLEAR POWER PLANT

P. O. BOX 215 BUCHANAN, N. Y. 10511

TELEPHONE: 914-739-8200



August 8, 1980
IP-MEA-9553

Docket No. 50-286
License No. DPR-647


Boyce H. Grier, Director
Office of Inspection and Enforcement
Region 1
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406

Subject: I. E. Bulletin 80-19

Dear Mr. Grier:

Please be advised that none of the mercury-wetted relays referenced in I. E. Bulletin 80-19 are utilized in the Reactor Protection System at Indian Point 3. We, therefore, conclude that the actions in this bulletin are not applicable to our facility and no further action is required.

An estimated four hours was expended in the conduct of review of this bulletin.

Very truly yours,

S. S. Zulla
Resident Manager

MEA/bam

cc: U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Division of Reactor Operations Inspection
Washington, D. C. 20555

Mr. George T. Berry
Power Authority of the State of New York
10 Columbus Circle
New York, New York 10019

Resident Inspector T. Rebelowski
G. Wilverding, NYO
James Davis (SRC), NYO
J. P. Bayne, NYO
R. L. Goyette, NYO
File 3-201

8009220 030