

ADMSB

POWER AUTHORITY OF THE STATE OF NEW YORK

INDIAN POINT NO. 3 NUCLEAR POWER PLANT


P. O. BOX 215 BUCHANAN, N. Y. 10511

TELEPHONE: 914-739-8200



May 8, 1981
IP-SLM-13533

Docket No. 50-286
License No. DPR-54



Boyce H. Grier, Director
Office of Inspection and Enforcement
Region 1
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406

Subject: I.E. Bulletin 81-2

Dear Mr. Grier:

As a result of our investigation, the valves identified in this bulletin are not installed, or maintained as spares for installation, in safety-related systems or as PORV block valves. A total of 30 man hours were expended in preparation of this response.

Very truly yours,

John C. Brons
John C. Brons
Resident Manager

SLM/bam

cc: Director of the Nuclear Regulatory Commission
Office of Inspection and Enforcement
Washington, D. C. 20555

Resident Inspector T. Rebelowski

State of New York)
County of Westchester) ss.:

On this 8 Day of May, 1981 before me personally appeared John C. Brons, to me known and known to me to be the person who signed the above letter.

NICHOLAS A. CARLUCCI
Notary Public, State of New York
No. 4651851, Putnam County
Commission Expires March 30, 1983

8106040476

Q

Nicholas A. Carlucci