

Stephen E. Quinn
Vice President

Consolidated Edison Company of New York, Inc.
Indian Point Station
Broadway & Bleakley Avenue
Buchanan, NY 10511
Telephone (914) 734-5340

July 22, 1997

Re: Indian Point Unit No. 2
Docket No. 50-247

Document Control Desk
US Nuclear Regulatory Commission
Mail Station P1-137
Washington, DC 20555

SUBJECT: Indian Point Unit 2 Cycle 14 Core Operating Limit Report
(COLR)

In accordance with Indian Point Unit 2 Technical Specifications Section 6.9.1.11,
enclosed is the IP2 COLR for Cycle 14.

Should you have any questions regarding this matter, please contact Mr. Charles
W. Jackson, Manager, Nuclear Safety and Licensing.

Very truly yours,



C: Mr. Hubert J. Miller
Regional Administrator - Region I
US Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, PA 19406

Mr. Jefferey F. Harold, Project Manager
Project Directorate I-1
Division of Reactor Projects I/II
US Nuclear Regulatory Commission
Mail Stop 14B-2
Washington, DC 20555

Senior Resident Inspector
US Nuclear Regulatory Commission
PO Box 38
Buchanan, NY 10511

A0011/

9708060019 970722
PDR ADOCK 05000247
P PDR

