

Stephen E. Quinn
Vice President

Consolidated Edison Company of New York, Inc.
Indian Point Station
Broadway & Bleakley Avenue
Buchanan, NY 10511
Telephone (914) 734-5340

September 30, 1997

Re: Indian Point Unit No. 2
Docket No. 50-247

Mr. Hubert J. Miller
Regional Administrator
US Nuclear Regulatory Commission
Region 1
475 Allendale Road
King of Prussia, PA 19406

SUBJECT: Re-Instatement of Senior Reactor Operator's License

This letter is being submitted by Consolidated Edison Company of New York, Inc. ("Con Edison") on behalf of Christopher Massaro, requesting re-instatement of his Senior Reactor Operator's License (SOP-11130) at Indian Point Unit 2. Pursuant to 10 CFR 55.47, the Con Edison also requests a waiver of the requirement for the applicant to pass a written examination and an operating test based on the information provided below.

Mr. Massaro's license was terminated upon his resignation in April 1997. Prior to his resignation, Mr. Massaro successfully passed the 1996 annual requalification exam and discharged his responsibilities competently and safely. Subsequent to his resignation, Mr. Massaro was re-employed by Con Edison in July 1997. Upon Mr. Massaro's re-employment, he successfully completed the licensed operator continuing training cycle missed during his absence.

To ensure that Mr. Massaro is up-to-date with regard to licensed activities, an annual requalification exam was administered to him in accordance with 10 CFR 55.59. The exam consisted of a comprehensive written exam and an annual operating test. The operating test consisted of two simulator scenarios and five job performance measures (JPMs). Mr. Massaro received an 89.6% on the written exam, passed both simulator scenarios and passed four of the five JPMs. Based on these results, Con Edison is satisfied that Mr. Massaro is up-to-date and can competently and safely discharge his responsibilities. Additionally, Con Edison requests a waiver of the performance of forty hours of shift functions pursuant to 10 CFR 55.53 as Mr. Massaro's license will not be active. If, however, Con Edison needs to activate Mr. Massaro's license, the requirements of 10 CFR 55.53 (f) will be satisfied.

Enclosed please find the applicant's medical record (NRC Form 396) and license application (NRC Form 398).


9710080151 970930
PDR ADOCK 05000247
V PDR



1/0
Le42

Your cooperation in this matter is greatly appreciated. Should you have any questions regarding this matter, please contact Mr. John Ferrick, Manager, Operator Training at (914) 271-7200.

Very truly yours,



C: W/O Attachments

Mr. Stuart A. Richards, Chief
Operator Licensing Branch,
Mail Stop OWFN 10D-22
US Nuclear Regulatory Commission
Washington, DC 20555

Document Control Desk
US Nuclear Regulatory Commission
Mail Station P1-137
Washington, DC 20555

Mr. Jefferey F. Harold, Project Manager
Project Directorate I-1
Division of Reactor Projects I/II
US Nuclear Regulatory Commission
Mail Stop 14B-2
Washington, DC 20555

Senior Resident Inspector
US Nuclear Regulatory Commission
PO Box 38
Buchanan, NY 10511

Mr. Glenn Meyer, Chief
Operator Licensing and Human
Performance Branch
Division of Reactor Safety - Region I
US Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, PA 19406-1498