

Indian Point 3  
Nuclear Power Plant  
P.O. Box 215  
Buchanan, New York 10511  
914 739.8200



January 11, 1988  
IP3-88-002  
JAS-88-001

Docket No. 50-286  
License No. DPR-64

Mr. William T. Russell  
Regional Administrator  
Region I  
U.S. Nuclear Regulatory Commission  
631 Park Avenue  
King of Prussia, PA 19406

Subject: NRC Compliance Bulletin No. 87-02  
Fastener Testing To Determine Conformance  
With Applicable Material Specifications

Dear Mr. Russell:

This letter is to advise you that the report requested by Action Items 5 and 6 of the subject bulletin will not be submitted within the requested time frame. This delay is due to the unavailability of complete laboratory test results until the end of January, 1988.

The Authority will submit the reports by February 12, 1988. Should you or your staff have any questions regarding this matter, please contact Mr. M. P. Cass of my staff.

Sincerely,

A handwritten signature in cursive script, appearing to read 'W. A. Josiger'.

W. A. Josiger  
Resident Manager  
Indian Point Unit 3 Nuclear Power Plant

WAJ:JAS:lh

8801200422 880111  
PDR ADOCK 05000286  
Q PDR

IE 11  
1/0

cc: Document Control Desk (original)  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Resident Inspector's Office  
Indian Point 3  
U.S. Nuclear Regulatory Commission  
P.O. Box 337  
Buchanan, NY 10511