

Indian Point 3
Nuclear Power Plant
P.O. Box 215
Buchanan, New York 10511
914 736.8001



**New York Power
Authority**

L. M. Hill
Site Executive Officer

November 14, 1995
IPN-95-115

U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, D.C. 20555

SUBJECT: Indian Point 3 Nuclear Power Plant
Docket No. 50-286
License No. DPR-64
Licensee Event Report Number 95-014-01
**"Low Pressure Operation Placed the Plant Outside Design Basis
Due To Inadequate Procedures and Improper Document Use"**

Dear Sir:

The Power Authority is submitting the attached revised Licensee Event Report (LER) 95-014-01 to identify our additional findings resulting from a root cause evaluation that examined this event and similar events to enhance human performance in plant operation. Also, this revision provides an update on the status of our corrective actions.

No new commitments are being made by the Power Authority in this letter.

If there are any questions, please contact Mr. K. Peters of my staff at (914) 736-8023.

Very truly yours,

A handwritten signature in black ink, appearing to read 'L. M. Hill'.

L. M. Hill
Site Executive Officer
Indian Point 3 Nuclear Power Plant

Attachment
cc: See next page

9511270063 951114
PDR ADOCK 05000286
S PDR

IF22
11

cc: Mr. Thomas T. Martin
Regional Administrator
Region I
U.S. Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, Pennsylvania 19406-1415

INPO Record Center
700 Galleria Parkway
Atlanta, Georgia 30339-5957

U.S. Nuclear Regulatory Commission
Resident Inspectors' Office
Indian Point 3 Nuclear Power Plant