Indian Point 3 Nuclear Power Plant P.O. Box 215 Buchanan, New York 10511 914 736.8001



Robert J. Barrett
Site Executive Officer

October 15, 1997 IPN-97-143

U.S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, D.C. 20555

SUBJECT:

Indian Point 3 Nuclear Power Plant

Docket No. 50-286 License No. DPR-64

Licensee Event Report # 97-025-00

Automatic Reactor Trip due to a High Resistance Contact on a Reactor Protection Relay While Testing An Analog Channel

Dear Sir:

The attached Licensee Event Report (LER) 97-025-00 is hereby submitted as required by 10 CFR 50.73. This event is of the type defined in 10 CFR 50.73 (a)(2)(iv).

Also attached is the commitments made by the Authority in this LER.

Very truly yours,

Robert J. Barrett Site Executive Officer

Indian Point 3 Nuclear Power Plant

**Attachments** 

cc: See next page

9710240038 971015 PDR ADDCK 05000286 PDR PDR TE33/1



Docket No. 50-286 IPN-97-143 Page 2 of 2

cc: Mr. Hubert J. Miller
Regional Administrator
Region I
U. S. Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, Pennsylvania 19406-1415

INPO Record Center 700 Galleria Parkway Atlanta, Georgia 30339-5957

U.S. Nuclear Regulatory Commission Resident Inspectors' Office Indian Point 3 Nuclear Power Plant

Docket No. 50-286 IPN-97-143 Attachment Page 1 of 1

## **COMMITMENT LIST**

Number	Commitment	Due
IPN-97-143-01	I&C Engineering will develop a preventative maintenance program for reactor protection relays. This will be completed by May 15, 1998, in time for implementation during the next refueling outage (RO-10). This outage is planned for 1999.	05/15/98
IPN-97-143-02	I&C will implement the reactor protection relay preventative maintenance program during the next refueling outage (RO-10). This outage is planned for the latter part of the year 1999.	09/1999