

DOCKET NO. 50-286
 UNIT NAME INDIAN POINT NO. 3
 DATE 2-2-98
 COMPLETED BY T. Orlando
 TELEPHONE (914) 736-8340
 IPN-98-016
 ATTACHMENT I
 PAGE 4 of 5

UNIT SHUTDOWNS AND POWER REDUCTIONS

REPORT MONTH December 1997
 Rev. 1

NO.	DATE	TYPE 1	DURATION (HOURS)	REASON 2	METHOD OF SHUTTING DOWN REACTOR 3	LICENSEE EVENT REPORT #	SYSTEM CODE 4	COMPONENT CODE 5	CAUSE & CORRECTIVE ACTION TO PREVENT RECURRENCE
8	971218	F	274.13	A	1	97-032-00	CF	CKTBRK	PLANT SHUTDOWN FOR AN INOPERABLE 480 VOLT BUS 6A DUE TO A FAILURE OF THE 32 RESIDUAL HEAT REMOVAL (RHR) PUMP CIRCUIT BREAKER TO OPEN FOLLOWING PERFORMANCE OF SURVEILLANCE TEST 3PT-M18, "RHR PUMP FUNCTIONAL TEST." 480 VOLT BUS 6A REMAINED ENERGIZED BUT WAS CONSIDERED INOPERABLE.
9	971230	S	48	B	N/A	N/A	N/A	N/A	TRANSITION FROM FORCED OUTAGE TO PLANNED. PERFORMED VARIOUS PLANNED MAINTENANCE AND SURVEILLANCE ACTIVITIES.

1
 F: Forced
 S: Scheduled

2
 Reason:
 A- Equipment
 B- Maintenance or Test
 C- Refueling
 D- Regulatory Restriction
 E- Operator Training & Licensee Examination
 F- Administrative
 G- Operational Error
 H- Other (Explain)

3
 Method:
 1-Manual
 2-Manual Scram
 3-Automatic Scram
 4-Other (Explain)

4
 Exhibit G - Instructions
 for Preparation of Data
 Entry Sheets for Licensee
 Event Report (LER) File
 (NUREG - 0161)

5
 Exhibit 1 -
 Same Source

9802250276 980211
 PDR ADDCK 05000286
 R PDR