

John D. O'Toole
Vice President

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, NY 10003
Telephone (212) 460-2533

April 3, 1984

Re: Indian Point Unit Nos. 1 and 2
Docket Nos. 50-03 and 50-247

Dr. Thomas E. Murley, Regional Administrator
Region I
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pa. 19406


Dear Dr. Murley:

In accordance with 10 CFR 50.54(q) Con Edison submits herewith a controlled copy of page changes to Book II of the Emergency Procedures Document (EPD) for Indian Point Unit Nos. 1 and 2. These changes do not reduce the effectiveness of the Emergency Plan and the Emergency Plan continues to meet the standard of 50.47(b) and the requirements of Appendix E to 10 CFR 50.

Please sign and return controlled copy sign off sheet as indicated thereon, to acknowledge receipt of these changes.

Should you or your staff have any questions, please contact us.

Very truly yours,



attach.

cc: Document Control Desk (2 copies)
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. T. Foley, Senior Resident Inspector
U. S. Nuclear Regulatory Commission
P. O. Box 38
Buchanan, New York 10511

8404160088 840403
PDR ADDCK 05000003
PDR

A045
11