

Murray Selman
Vice President

Consolidated Edison Company of New York, Inc.
Indian Point Station
Broadway & Bleakley Ave.
Buchanan, NY 10511
Telephone (914) 737-8116

October 4, 1985

RE: Indian Point Unit Nos. 1 and 2
Docket Nos. 50-03 and 50-247

Dr. Thomas E. Murley
Regional Administrator-Region I
U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406

Dear Dr. Murley:

In accordance with 10 CFR 50.54(q), Con Edison submits herewith a controlled copy of page changes to Books 1 and 2 of the Emergency Procedures Document (EPD) for Indian Point Unit Nos. 1 and 2. These changes do not reduce the effectiveness of the Emergency Plan and the Emergency Plan continues to meet the standard of 50.47 (b) and the requirements of Appendix E to 10 CFR 50.

As recommended in Generic Letter 81-17, entitled "Privacy and Proprietary Materials in Emergency Plans", the following pages, as marked, are designated as proprietary:

	<u>Procedure</u>	<u>Pages</u>
Book 2	IP-1001	IP-1001-4
	IP-1002	IP-1002-1 through 8,12,13,14
	IP-1015	IP-1015-1,4,8 through 15
	IP-1019	IP-1019-2
	IP-1023	IP-1023-6,13
	IP-1026	IP-1026-4
	IP-1027	IP-1027-11,12
	IP-1035	IP-1035-7
	IP-1043	IP-1043-2
	<u>EPD Section</u>	<u>Pages</u>
Book 1	POM	POM-7
	ED	ED-13
	STHP	STHP-2
	EOF COMM.	COMM. No. 1-6
	EOF COMM.	COMM. No. 2-6

8511040218 851004
PDR ADDCK 05000003
F PDR

X005
1/2


October 4, 1985

RE: Indian Point Unit Nos. 1 and 2
Docket Nos. 50-03 and 50-247

Please sign and return the controlled copy sign off sheet as indicated thereon acknowledging receipt of these changes.

Should you or your staff have any questions, please contact us.

Very truly yours,

A handwritten signature in cursive script, appearing to read "Murray Selman".

Attachments:

cc: Document Control Desk (2 copies)
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Senior Resident Inspector
U.S. Nuclear Regulatory Commission
P.O. Box 38
Buchanan, NY 10511

14.397.9.9.2