

Stephen B. Bram
Vice President

Consolidated Edison Company of New York, Inc.
Indian Point Station
Broadway & Bleakley Avenue
Buchanan, NY 10511
Telephone (914) 737-8116

February 28, 1989


Re: Indian Point Unit Nos. 1 & 2
Docket Nos. 50-003 & 50-247

Document Control Desk
US Nuclear Regulatory Commission
Mail Station P1-137
Washington, DC 20555

Enclosed as Attachment A is a statistical summary report of personnel monitoring at Indian Point Unit Nos. 1 and 2 for the calendar year 1988. This report is submitted pursuant to Title 10, Code of Federal Regulations, Section 20.407.

Enclosed as Attachment B is the Annual Radiation Exposure Report. This report is submitted pursuant to Section 6.9.1.4 of Appendix A to Facility Operating Licensee DPR-26.

Very truly yours,



Attachments

cc: Mr. William Russell
Regional Administrator - Region I
US Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, PA 19406-1498

Mr. Donald S. Brinkman, Project Manager
Project Directorate I-1
Division of Reactor Projects I/II
US Nuclear Regulatory Commission
Mail Stop 14B-2
Washington, DC 20555

Senior Resident Inspector
US Nuclear Regulatory Commission
PO Box 38
Buchanan, NY 10511

8903140166 890228
PER ADUCK 05000008
R PIC

IESG
11