

John D. O'Toole
Vice President

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, NY 10003
Telephone (212) 460-2533

December 14, 1984

Re: Indian Point Unit Nos. 1 and 2
Docket Nos. 50-03 and 50-247

Dr. Thomas E. Murley, Regional Administrator
Region I
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406

Dear Dr. Murley:

In accordance with 10 CFR 50.54(q) Con Edison submits herewith a controlled copy of page changes to Books I & II of the Emergency Procedures Document (EPD) for Indian Point Unit Nos. 1 and 2. These changes do not reduce the effectiveness of the Emergency Plan and the Plan continues to meet the standard of 50.47(b) and the requirements of Appendix E to 10 CFR 50.

As recommended in Generic Letter 81-17 "Privacy and Proprietary Materials in Emergency Plans" the following pages, as marked are designated as proprietary:

Book I

<u>EPD Section</u>	<u>Pages</u>
CRO	CRO-1 and 3
POM	POM-7
ED	ED-2,3 and 13
ORAD	ORAD-1 and 4
STHP	STHP-2
EOF COMM	COMM NO. 1-6, 2-1, 2-2 and 2-6

Book II

<u>Implementation Procedure</u>	<u>Pages</u>
IP-1002	IP-1002 - 1 through 7 and 11 through 13

Please sign and return controlled copy sign off sheet as indicated thereon, to acknowledge receipt of these changes.

8501070220 841214
PDR ADDCK 05000003
F PDR

[Handwritten signature]
1/1


T. E. Murley

-2-

December 14, 1984

Should you or your staff have any questions, please contact us.

Very truly yours,

A handwritten signature in cursive script, reading "John D. O'Toole", with a long horizontal flourish extending to the right.

John D. O'Toole
Vice President

Attachment

CC: Document Control Desk (2 copies)
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Senior Resident Inspector
U. S. Nuclear Regulatory Commission
Post Office Box 38
Buchanan, New York 10511