

NFPA 805 FAQ Status and History

| FAQ # | Date | Topic / Comment | ADAMS # |
|---------|----------|--|-------------------------|
| 06-0001 | 7/06 | Alternate method for engineering evaluations. | ML061440419 |
| | 7/06 | Staff Response to Revision 0 | ML062060303 |
| | 12/14/06 | Closure Memo | ML063480139 |
| | | Status: Withdrawn | |
| 06-0002 | 7/06 | Order of questions for change analysis screening. | ML061440420 |
| | 7/06 | Staff Response to Revision 0 | ML062060303 |
| | 10/06 | Revision 1 | ML063170357 |
| | 11/06 | Revision 2 | ML063350515 |
| | 1/4/07 | Closure Memo | ML070030276 |
| | | | Status: Resolved |
| 06-0003 | 7/06 | Change analysis screening. | ML061440422 |
| | 7/06 | Staff Response to Revision 0 | ML062060303 |
| | 10/06 | Revision 1 | ML063170355 |
| | 1/4/07 | Closure Memo | ML070030242 |
| | | Status: Resolved | |
| 06-0004 | 7/06 | Clarify the NFPA 805 Chapter 3 and 4 relationship for "required" Fire Protection systems and features. | ML061440430 |
| | 7/06 | Staff Response to Revision 0 | ML062060303 |
| | 11/06 | Staff Response to Revision 0 | ML063350442 |
| | 8/21/08 | Closure Memo | ML082330386 |
| | | Status: Withdrawn | |
| 06-0005 | 8/06 | Guidance on Fire Protection Program related changes. | ML062350095 |
| | 11/06 | Revision 1 | ML063180544 |
| | 8/07 | Staff Response to Revision 1 | ML072400021 |
| | 10/07 | Revision 2 | ML072820015 |
| | 10/07 | Staff Response to Revision 2 | ML073060462 |
| | 8/11/08 | Closure Memo | ML081690332 |
| | | Status: Withdrawn | |
| 06-0006 | 8/06 | High-low pressure interface definition and NEI 00-01 / NFPA 805 discrepancies. | ML062350109 |
| | 9/06 | Staff Response to Revision 0 | ML062890268 |
| | 10/06 | Revision 1 | ML063170360 |
| | 12/06 | Revision 2 | ML063540308 |
| | 3/07 | Staff response to Revision 2 | ML070660071 |
| | 3/12/07 | Closure Memo | ML070030117 |
| | | Status: Resolved | |
| 06-0007 | 8/06 | NFPA 805 Chapter 3 requirements for Fire Brigades. | ML062350121 |
| | 10/06 | Staff Response to Revision 0 | ML063170365 |
| | 12/06 | Revision 1 | ML070030325 |
| | 2/07 | Revision 2 | ML070510442 |
| | 5/07 | Staff Response | ML071380338 |
| | 6/07 | Revision 3 | ML071550408 |
| | 11/13/07 | Closure Memo | ML072560733 |
| | | Status: Resolved | |
| 06-0008 | 9/06 | Alternate method for engineering evaluations. | ML062860250 |
| | 11/06 | Staff Response to Revision 0 | ML063350442 |

NFPA 805 FAQ Status and History

| FAQ # | Date | Topic / Comment | ADAMS # |
|---------|---------|--|-------------|
| | 2/07 | Revision 1 | ML070510499 |
| | 3/07 | Staff Response to Revision 1 | ML070640544 |
| | 3/07 | Revision 2 | ML070800007 |
| | 4/07 | Revision 3 | ML071020160 |
| | 4/07 | Attachment to Revision 3 | ML071020169 |
| | 4/07 | Staff Response to Revision 3 | ML071380177 |
| | 4/07 | Revision 4 | ML071080099 |
| | 4/07 | Staff Response to Revision 4 | ML071380182 |
| | 5/07 | Revision 5 | ML071340180 |
| | 7/07 | Staff Response to Revision 5 | ML072050214 |
| | 8/07 | Revision 6 | ML072400065 |
| | 9/07 | Staff Response to Revision 6 | ML072740231 |
| | 10/07 | Revision 7 | ML072820016 |
| | 12/07 | Staff Response to Revision 7 | ML073370775 |
| | 12/07 | Revision 8 | ML073370025 |
| | 10/08 | Staff Response to Revision 8 | ML083010063 |
| | 2/09 | Revision 9 | ML090560170 |
| | 3/12/09 | Closure Memo | ML073380976 |
| | | Status: Resolved | |
| 06-0011 | 9/06 | Clarify "Appendix R" III.G.3 compliance transition. | ML062890271 |
| | 11/06 | Staff Response to Revision 0 | ML063350442 |
| | 2/07 | Revision 1 | ML070510505 |
| | 8/07 | Staff Response to Revision 1 | ML072400024 |
| | 9/07 | Revision 2 | ML072740248 |
| | 3/4/08 | Closure Memo | ML080300121 |
| | | Status: Resolved | |
| 06-0012 | 9/06 | Clarify operator manual action transition in NEI 04-02 Appendix B. | ML062860255 |
| | 10/06 | Revision 1 | ML063170362 |
| | 11/06 | Staff Response to Revision 1 | ML063350442 |
| | 3/07 | NEI Response to Staff Comments | ML070850658 |
| | 3/07 | Revision 2 | ML070850610 |
| | 4/07 | Staff Response to Revision 2 | ML071380186 |
| | 5/07 | Revision 3 | ML071380229 |
| | 6/07 | Revision 4 | ML071570260 |
| | 9/07 | Staff Response to Revision 4 | ML072820168 |
| | 10/07 | Staff Response to Revision 4 | ML072820170 |
| | 11/07 | Revision 5 | ML073320028 |
| | 1/24/08 | Closure Memo | ML072340368 |
| | | Status: Resolved | |
| 06-0016 | 12/06 | Ignition source counting guidance for electrical cabinets. | ML070030348 |
| | 3/07 | Staff Response to Revision 0 | ML070640555 |
| | 4/07 | Revision 1 | ML071020174 |
| | 10/5/07 | Closure Memo | ML072700475 |
| | | Status: Resolved | |
| 06-0017 | 12/06 | Ignition source counting guidance for high energy arcing faults. | ML070030383 |

NFPA 805 FAQ Status and History

| FAQ # | Date | Topic / Comment | ADAMS # |
|---------|----------|--|-------------|
| | 5/07 | Revision 1 | ML071350432 |
| | 5/07 | Staff Response to Revision 1 | ML071380343 |
| | 6/07 | Revision 2 | ML071550406 |
| | 9/26/07 | Closure Memo | ML072500300 |
| | | Status: Resolved | |
| 06-0018 | 12/06 | Ignition source counting guidance for main control board. | ML070030427 |
| | 3/07 | Staff Response to Revision 0 | ML070640562 |
| | 4/07 | Revision 1 | ML071020181 |
| | 9/26/07 | Closure Memo | ML072500273 |
| | | Status: Resolved | |
| 06-0019 | 12/06 | Definition of the terms "power block" and "plant" in NFPA 805. | ML070030437 |
| | 2/07 | Staff Response to Revision 0 | ML070510365 |
| | 5/07 | Revision 1 | ML071340184 |
| | 9/07 | Revision 2 | ML072550063 |
| | 10/07 | Revision 3 | ML072740255 |
| | 10/07 | Staff Response to Revision 3 | ML073060471 |
| | 11/07 | Revision 4 | ML073060545 |
| | 3/5/08 | Closure Memo | ML080510224 |
| | | Status: Resolved | |
| 06-0020 | 12/06 | Definition of "applicable NFPA standards" in NFPA 805. | ML070030443 |
| | 2/07 | Staff Response to Revision 0 | ML070510369 |
| | 5/07 | Revision 1 | ML071340188 |
| | 11/28/07 | Closure Memo | ML072420286 |
| | | Status: Resolved | |
| 06-0021 | 12/06 | Clarification that cable air drops are acceptable. | ML070030457 |
| | 2/07 | Staff Response to Revision 0 | ML070510417 |
| | 5/07 | Revision 1 | ML071340192 |
| | 11/13/07 | Closure Memo | ML072420306 |
| | | Status: Resolved | |
| 06-0022 | 12/06 | Identify a list of flame propagation tests which are considered acceptable by the NRC. | ML070030459 |
| | 7/07 | Staff Response to Revision 0 | ML072050222 |
| | 8/07 | Revision 1 | ML072340055 |
| | 9/07 | Staff Response to Revision 1 | ML072740236 |
| | 11/08 | Revision 2 | ML083010053 |
| | 3/09 | Revision 3 | ML090830220 |
| | 5/5/09 | Closure Memo | ML091240278 |
| | | Status: Resolved | |
| 06-0023 | 12/06 | Exception for diesel generator day tanks located within diesel generator buildings. | ML070030470 |
| | 10/3/07 | Closure Memo | ML072700552 |
| | | Status: Withdrawn | |
| 06-0024 | 12/06 | Define what "adequate clearance" is for energized equipment. | ML070030472 |
| | 4/07 | Staff Response to Revision 0 | ML071380189 |

NFPA 805 FAQ Status and History

| FAQ # | Date | Topic / Comment | ADAMS # |
|---------|----------|--|-------------|
| | 8/07 | Revision 1 | ML072700542 |
| | 10/16/07 | Closure Memo | ML072740225 |
| | | Status: Resolved | |
| 06-0025 | 12/06 | Define minimum acceptable Pre-Fire Plan scope. | ML070030476 |
| | 1/07 | Staff Response to Revision 0 | ML070300588 |
| | 5/07 | Revision 1 | ML071340194 |
| | 11/07 | Revision 2 | ML073200459 |
| | 12/07 | Revision 3 | ML073510082 |
| | 12/07 | Staff Response to Revision 3 | ML073510074 |
| | 12/07 | NEI Response to Staff Comments | ML073550017 |
| | 12/07 | Revision 4 | ML073550021 |
| | 3/08 | Revision 5 | ML080700157 |
| | 5/08 | Staff Response to Revision 5 | ML081360203 |
| | 8/21/08 | Closure Memo | ML082330365 |
| | | Status: Withdrawn | |
| 06-0026 | 12/06 | Clarification of NFPA code requirements for Fire Brigade equipment maintenance. | ML070030480 |
| | 4/07 | Staff Response to Revision 0 | ML071380194 |
| | 10/15/07 | Closure Memo | ML072560564 |
| | | Status: Withdrawn | |
| 06-0027 | 5/07 | Clarification of the term "where provided" with respect to fire extinguishers. | ML071380236 |
| | 10/22/08 | Closure Memo | ML082700328 |
| | | Status: Resolved | |
| 06-0028 | 12/06 | Clarification of the intent of the scope and / or depth of the fire safety training for all plant employees. | ML070030489 |
| | 2/07 | Staff Response to Revision 0 | ML070510427 |
| | 5/07 | Revision 1 | ML071340195 |
| | 5/07 | Staff Response to Revision 1 | ML071380349 |
| | 6/07 | Revision 2 | ML071550415 |
| | 10/17/07 | Closure Memo | ML072740233 |
| | | Status: Resolved | |
| 07-0030 | 1/09 | Risk of recovery actions | ML090290218 |
| | | Status: Open | |
| 07-0031 | 5/07 | Miscellaneous fire ignition frequency binning issues. | ML071380238 |
| | 10/07 | Staff Response to Revision 0 | ML073060480 |
| | 12/17/07 | Closure Memo | ML072840658 |
| | | Status: Resolved | |
| 07-0032 | 7/07 | Clarify relationship between 50.48(a), 50.48(c), and GDC 3. | ML071930378 |
| | 10/07 | Staff Response to Revision 0 | ML073060492 |
| | 3/08 | Revision 1 | ML080700411 |
| | 5/08 | Staff Response to Revision 1 | ML081300689 |
| | 5/08 | Revision 2 | ML081300697 |
| | 8/20/08 | Closure Memo | ML081400292 |
| | | Status: Resolved | |
| 07-0033 | 7/07 | Transition of existing engineering equivalency evaluations. | ML071930379 |

NFPA 805 FAQ Status and History

| FAQ # | Date | Topic / Comment | ADAMS # |
|---------|-----------|---|-------------|
| | 9/07 | Staff Response to Revision 0 | ML072700037 |
| | 1/08 | Revision 1 | ML073550023 |
| | 8/28/08 | Closure Memo | ML082380395 |
| | | Status: Resolved | |
| 07-0035 | 6/07 | Bus duct counting guidance for high energy arcing faults. | ML071650151 |
| | 12/07 | Staff Response to Revision 0 | ML073540262 |
| | 7/08 | NEI Response to Staff Comments | ML081960709 |
| | 3/09 | Revision 1 | ML090850012 |
| | 4/09 | Staff Response to Revision 1 | ML090930500 |
| | 6/09 | Revision 2 | ML091610189 |
| | 6/16/09 | Closure Memo | ML091620572 |
| | | Status: Resolved | |
| 07-0036 | 8/07 | Table B-1 Update. | ML072320155 |
| | 9/07 | Staff Response to Revision 0 | ML072700038 |
| | 1/08 | Revision 1 | ML073550025 |
| | 8/28/08 | Closure Memo | ML082380547 |
| | | Status: Resolved | |
| 07-0038 | 9/07 | Multiple Spurious Operation Resolution. | ML072740262 |
| | 10/07 | Staff Response to Revision 0 | ML073060506 |
| | 7/08 | Revision 1 | ML082100034 |
| | 9/08 | Staff Response to Revision 1 | ML082700815 |
| | | Status: Open | |
| 07-0039 | 9/07 | Table B-2 Update. | ML072740268 |
| | 11/07 | Staff Response to Revision 0 | ML073330556 |
| | 4/08 | Revision 1 | ML080910136 |
| | 9/08 | Revision 2 | ML091420138 |
| | 1/15/2010 | Closure Memo | ML091320068 |
| | | Status: Resolved | |
| 07-0040 | 10/07 | Clarification on Non-Power Operations. | ML073060550 |
| | 11/07 | Staff Response to Revision 0 | ML073170227 |
| | 3/08 | Revision 1 | ML080720027 |
| | 4/08 | Staff Response to Revision 1 | ML081150739 |
| | 6/08 | Revision 2 | ML081430041 |
| | 6/08 | Staff Response to Revision 2 | ML081790387 |
| | 7/08 | Revision 3 | ML081960523 |
| | 7/08 | Revision 4 | ML082070249 |
| | 8/11/08 | Closure Memo | ML082200528 |
| | | Status: Resolved | |
| 07-0041 | 11/07 | Chapter 3 Codes and Standards | ML073310447 |
| | 7/2/08 | Closure Memo | ML081690302 |
| | | Status: Withdrawn | |
| 08-0042 | 1/08 | Fire propagation from electrical cabinets. | ML080230438 |
| | 6/09 | Draft Interim Position for Comment | ML091460350 |
| | 8/4/09 | Closure Memo | ML092110537 |
| | | Status: Resolved | |
| 08-0043 | 6/08 | Cabinet fire location | ML081500507 |

NFPA 805 FAQ Status and History

| FAQ # | Date | Topic / Comment | ADAMS # |
|---------|---------|---|-------------|
| | 1/09 | Revision 1 | ML083540152 |
| | 6/09 | Draft Interim Position for Comment | ML091470266 |
| | 8/4/09 | Closure Memo | ML092120448 |
| | | Status: Resolved | |
| 08-0044 | 4/08 | Large spill oil fire size | ML081200099 |
| | 6/09 | Draft Interim Position for Comment | ML091540179 |
| | 8/4/09 | Closure Memo | ML092110516 |
| | | Status: Resolved | |
| 08-0045 | 4/08 | Fire Growth in Electrical Cabinets | ML081200117 |
| | 5/19/09 | Closure Memo | ML091240311 |
| | | Status: Withdrawn | |
| 08-0046 | 4/08 | Incipient Fire Detection Systems | ML081200120 |
| | 6/09 | Draft Interim Position for Comment | ML091750338 |
| | 7/09 | Public Comment | ML091970033 |
| | 7/09 | NEI Comment | ML092120076 |
| | 11/09 | Comment Resolution | ML093220197 |
| | 12/1/09 | Closure Memo | ML093220426 |
| | | Status: Resolved | |
| 08-0047 | 4/08 | Spurious Operation Probabilities | ML081200126 |
| | 9/08 | Revision 1 | ML082770662 |
| | 12/4/08 | Closure Memo | ML082950750 |
| | | Status: Resolved | |
| 08-0048 | 4/08 | Fire Ignition Frequency Update | ML081200291 |
| | 6/09 | Draft Interim Position for Comment | ML091590457 |
| | 7/09 | NEI Comment | ML091960437 |
| | 8/09 | Comment Resolution | ML092180383 |
| | 9/1/09 | Closure Memo | ML092190457 |
| | | Status: Resolved | |
| 08-0049 | 4/08 | Cable Tray Fire Propagation | ML081200309 |
| | 6/09 | Draft Interim Position for Comment | ML091470242 |
| | 7/30/09 | Closure Memo | ML092100274 |
| | | Status: Resolved | |
| 08-0050 | 4/08 | Manual Fire Non Suppression Probability | ML081200318 |
| | 6/09 | Draft Interim Position for Comment | ML091660045 |
| | 7/09 | NEI Comment | ML092030092 |
| | 8/09 | Comment Resolution | ML092180533 |
| | 8/09 | Second Draft Interim Position for Comment | ML092320044 |
| | 9/09 | NEI Comment | ML092430112 |
| | 9/09 | Comment Resolution | ML092510044 |
| | 9/14/09 | Closure Memo | ML092190555 |
| | | Status: Resolved | |
| 08-0051 | 1/09 | Hot short duration | ML083400188 |
| | 11/09 | Draft Interim Position for Comment | ML092330663 |
| | | Status: Open | |
| 08-0052 | 6/08 | Transient Fires | ML081500500 |
| | 6/09 | Draft Interim Position for Comment | ML091590505 |

NFPA 805 FAQ Status and History

| FAQ # | Date | Topic / Comment | ADAMS # |
|---------|--------|--------------------------------|-------------|
| | 8/4/09 | Closure Memo | ML092120501 |
| | | Status: Resolved | |
| 08-0053 | 9/08 | Kerite Cable Classification | ML082660021 |
| | 7/09 | Kerite Cable Fire Test | ML092080059 |
| | | Status: Open | |
| 09-0056 | 2/09 | Radioactive Release Transition | ML090490170 |
| | 12/09 | NEI Response to Revision 1 | ML100060137 |
| | | Status: Open | |
| 09-0057 | 6/09 | Safe Shutdown Strategy Change | ML091811059 |
| | 8/09 | Industry presentation slides | ML092440760 |
| | 9/09 | Staff Response to Revision 0 | ML092740681 |
| | 11/09 | NEI Response to Staff Comments | ML093020129 |
| | 11/09 | Revision 1 | ML093020058 |
| | 12/09 | Staff Response to Revision 1 | ML093440733 |
| | | Status: Open | |

NFPA 805 FAQ Meeting Documents

| Meeting Date | Document | ADAMS # |
|--------------------|-----------------|-------------|
| July 20, 2006 | Meeting Notice | ML061870560 |
| | Meeting Summary | ML062080126 |
| August 24, 2006 | Meeting Notice | ML062200116 |
| | Meeting Summary | ML062400278 |
| September 28, 2006 | Meeting Notice | ML062510281 |
| | Meeting Summary | ML062900031 |
| October 26, 2006 | Meeting Notice | ML062850488 |
| | Meeting Summary | ML063350031 |
| November 30, 2006 | Meeting Notice | ML063120170 |
| | Meeting Summary | ML063410377 |
| December 19, 2006 | Meeting Notice | ML063390132 |
| | Meeting Summary | ML070220420 |
| January 18, 2007 | Meeting Notice | ML070040380 |
| | Meeting Summary | ML070360630 |
| February 15, 2007 | Meeting Notice | ML070290267 |
| | Meeting Summary | ML070640531 |
| March 22, 2007 | Meeting Notice | ML070640417 |
| | Meeting Summary | ML071090164 |
| April 28, 2007 | Meeting Notice | ML070920255 |
| | Meeting Summary | ML071420174 |
| May 17, 2007 | Meeting Notice | ML071220176 |
| | Meeting Summary | ML071510425 |
| June 21, 2007 | Meeting Notice | ML071440064 |
| | Meeting Summary | ML071940375 |
| July 19, 2007 | Meeting Notice | ML071830089 |
| | Meeting Summary | ML072080246 |
| August 23, 2007 | Meeting Notice | ML072080206 |
| | Meeting Summary | ML072550213 |
| September 20, 2007 | Meeting Notice | ML072490032 |
| | Meeting Summary | ML073030222 |
| October 18, 2007 | Meeting Notice | ML072700706 |
| | Meeting Summary | ML073200763 |
| November 15, 2007 | Meeting Notice | ML073030183 |
| | Meeting Summary | ML073200936 |
| November 29, 2007 | Meeting Notice | ML073130319 |
| | Meeting Summary | ML073400502 |
| December 20, 2007 | Meeting Notice | ML073380193 |
| | Meeting Summary | ML080110048 |
| January 24, 2008 | Meeting Notice | ML073520255 |
| | Meeting Summary | ML080430163 |

NFPA 805 FAQ Meeting Documents

| | | |
|--------------------|-----------------|-------------|
| February 21, 2008 | Meeting Notice | ML080300019 |
| | Meeting Summary | ML080730007 |
| March 27, 2008 | Meeting Notice | ML080670491 |
| | Meeting Summary | ML081010524 |
| April 17, 2008 | Meeting Notice | ML080930031 |
| | Meeting Summary | ML081340232 |
| May 15, 2008 | Meeting Notice | ML081190589 |
| | Meeting Summary | ML081650440 |
| June 25, 2008 | Meeting Notice | ML081610475 |
| | Meeting Summary | ML082110365 |
| July 24, 2008 | Meeting Notice | ML081910077 |
| | Meeting Summary | ML082120456 |
| August 21, 2008 | Meeting Notice | ML082120444 |
| | Meeting Summary | ML082420605 |
| September 25, 2008 | Meeting Notice | ML082410057 |
| | Meeting Summary | ML083020365 |
| October 23, 2008 | Meeting Notice | ML082810073 |
| | Meeting Summary | ML083020373 |
| December 4, 2008 | Meeting Notice | ML083110480 |
| | Meeting Summary | ML083440443 |
| January 22, 2009 | Meeting Notice | ML083400513 |
| | Meeting Summary | ML090500303 |
| February 19, 2009 | Meeting Notice | ML090290128 |
| | Meeting Summary | ML090610080 |
| March 26, 2009 | Meeting Notice | ML090510521 |
| | Meeting Summary | ML091110439 |
| April 29, 2009 | Meeting Notice | ML090970071 |
| | Meeting Summary | ML091310489 |
| May 21, 2009 | Meeting Notice | ML091240223 |
| | Meeting Summary | ML091540222 |
| June 25, 2009 | Meeting Notice | ML091480367 |
| | Meeting Summary | ML092030286 |
| July 23, 2009 | Meeting Notice | ML091820467 |
| | Meeting Summary | ML092180158 |
| August 27, 2009 | Meeting Notice | ML092150782 |
| | Meeting Summary | ML092610720 |
| September 30, 2009 | Meeting Notice | ML092520068 |
| | Meeting Summary | ML092800490 |
| October 22, 2009 | Meeting Notice | ML092790189 |
| | Meeting Summary | ML093160704 |
| November 19, 2009 | Meeting Notice | ML093070211 |
| | Meeting Summary | ML093370023 |

NFPA 805 FAQ Meeting Documents

| | | |
|-------------------|-----------------|-------------|
| December 17, 2009 | Meeting Notice | ML093350283 |
| | Meeting Summary | ML100140123 |
| January 28, 2010 | Meeting Notice | ML100070344 |
| | Meeting Summary | |