



Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, N.Y. 10003

June 23, 1986

Mr. Brandon Chew
Assistant Sanitary Engineer
New York State Department of
Environmental Conservation
Region 3 Suboffice
White Plains, New York 10601

Re: Indian Point Generating Station
SPDES Permit No. NY 0004472

Dear Mr. Chew:

This is to confirm information I provided by telephone on June 18, 1986 to Ms. Judy Montgomery of your office concerning the discharge of a small amount of untreated sewage at the Indian Point Generating Station.

On June 18, 1986 at 8:45 AM, approximately 30 gallons of water containing untreated sanitary wastes and treated waste distillate tank wastes inadvertently overflowed from a hold-up tank and a fraction drained to the discharge canal. The treated distillate tank wastes, which are normally discharged to the discharge canal, were being held up for alternate disposal to enable the repair of distillate waste piping. In order to prevent recurrence, the Station air line to the air-operated pump which transferred wastes to the hold-up tank was disconnected. The air supply was closed and a "caution" tag applied which requires Senior Watch Supervisor or Support Facility Supervisor to reopen.

If you have any questions, please contact me (212-460-2522) or Leon Paretsky (212-460-2066).

Very truly yours,

Barry H. Cohen
Senior Environmental Eng.
Water & Waste Management

/gps

8607010145 860626
PDR ADOCK 05000003
S PDR