Page 1 of 2 03/03/2010 07:19:04

## Surry **Inspection / Activity Plan** 03/01/2010 - 06/30/2011

Report 22

Unit	Planne	ed Dates				No. of Staff
Number	Start	End	Inspection Activity		Title	
			OL EXAM	- INITIAL	EXAM PREP	4
1	06/28/2010	07/02/2010	V23336		SURRY/JULY 2010 EXAM AT POWER FACILITIES	
			PSB1EP	- EMERO	GENCY PREPAREDNESS INSPECTION	1
1, 2	07/12/2010	07/16/2010	IP 7111402		Alert and Notification System Evaluation	
1, 2	07/12/2010	07/16/2010	IP 7111403		Emergency Response Organization Augmentation Testing	
1, 2	07/12/2010	07/16/2010	IP 7111404		Emergency Action Level and Emergency Plan Changes	
1, 2	07/12/2010	07/16/2010	IP 7111405		Correction of Emergency Preparedness Weaknesses and Deficiencies	
1, 2	07/12/2010	07/16/2010	IP 71151		Performance Indicator Verification	
			OL EXAM	- INITIAL	EXAM - WEEK 1	4
1	07/26/2010	07/30/2010	V23336		SURRY/JULY 2010 EXAM AT POWER FACILITIES	
			OL EXAM	- INITIAL	EXAM - WEEK 2	4
1	08/02/2010	08/06/2010	V23336		SURRY/JULY 2010 EXAM AT POWER FACILITIES	
			EB3ISI	- UNIT 1	INSERVICE INSPECTION	1
1	11/01/2010	11/05/2010	IP 7111108P		Inservice Inspection Activities - PWR	
			PSB1-RP	- RP OC	CUPATIONAL WEEK 1	3
1, 2	11/01/2010	11/05/2010	IP 71124.01		Radiological Hazard Assessment and Exposure Controls	
1, 2	11/01/2010	11/05/2010	IP 71124.02		Occupational ALARA Planning and Controls	
1, 2	11/01/2010	11/05/2010	IP 71124.03		In-Plant Airborne Radioactivity Control and Mitigation	
1, 2	11/01/2010	11/05/2010	IP 71124.04		Occupational Dose Assessment	
1, 2	11/01/2010	11/05/2010	IP 71124.05		Radiation Monitoring Instrumentation	
1, 2	11/01/2010	11/05/2010	IP 71151		Performance Indicator Verification	
			PSB1-RP	- RP OC	CUPATIONAL WEEK2	2
1, 2	11/15/2010	11/19/2010	IP 71124.01		Radiological Hazard Assessment and Exposure Controls	
1, 2	11/15/2010	11/19/2010	IP 71124.02		Occupational ALARA Planning and Controls	
1, 2	11/15/2010	11/19/2010	IP 71124.03		In-Plant Airborne Radioactivity Control and Mitigation	
1, 2	11/15/2010	11/19/2010	IP 71124.04		Occupational Dose Assessment	
1, 2	11/15/2010	11/19/2010	IP 71124.05		Radiation Monitoring Instrumentation	
1, 2	11/15/2010	11/19/2010	IP 71151		Performance Indicator Verification	
			CDBI	- COMP	ONENT DESIGN BASIS INSPECTION	5
1, 2	01/10/2011	01/14/2011	IP 7111121		Component Design Bases Inspection	
1, 2	01/31/2011	02/04/2011	IP 7111121		Component Design Bases Inspection	
1, 2	02/14/2011	02/18/2011	IP 7111121		Component Design Bases Inspection	
1, 2	02/28/2011	03/04/2011	IP 7111121		Component Design Bases Inspection	
			TI-177	- TI-177	GASEOUS INTRUSION	3
1, 2	03/21/2011	03/25/2011	IP 2515/177		Managing Gas Accumulation In Emergency Core Cooling, Decay Heat Removal & Containment Spray System	

This report does not include INPO and OUTAGE activities. This report shows only on-site and announced inspection procedures.

Page 2 of 2

03/03/2010 07:19:04

Report 22

## Surry

**Inspection / Activity Plan** 03/01/2010 - 06/30/2011

Unit Number	Planne Start	Planned Dates Start End		Activity	Title	No. of Staff on Site
	-		EB3ISI		INSERVICE INSPECTION	1
2	04/25/2011	04/29/2011	IP 7111108F	<b>o</b>	Inservice Inspection Activities - PWR	
			PI&R	- PROBL	EM IDENTIFICATION AND RESOLUTION	4
1, 2	06/06/2011	06/10/2011	IP 71152B		Identification and Resolution of Problems	
1, 2	06/20/2011	06/24/2011	IP 71152B		Identification and Resolution of Problems	
			EB3HS	- HEAT S	SINK	1
1, 2	06/13/2011	06/17/2011	IP 7111107T	Γ	Heat Sink Performance	
			PSB1-RP	- RP PUE	BLIC RADIATION PROTECTION INSPT	4
1, 2	06/13/2011	06/17/2011	IP 71124.01		Radiological Hazard Assessment and Exposure Controls	
1, 2	06/13/2011	06/17/2011	IP 71124.04		Occupational Dose Assessment	
1, 2	06/13/2011	06/17/2011	IP 71124.06		Radioactive Gaseous and Liquid Effluent Treatment	
1, 2	06/13/2011	06/17/2011	IP 71124.07		Public Radiation Safety	
1, 2	06/13/2011	06/17/2011	IP 71124.08		Radioactive Solid Waste Processing and Radioactive Material Handling, Storage, and Transportation	
1, 2	06/13/2011	06/17/2011	IP 71151		Performance Indicator Verification	