

## Masters, Anthony

---

**From:** Fuller, Justin  
**Sent:** Friday, October 16, 2009 4:38 PM  
**To:** Masters, Anthony  
**Cc:** Moorman, James; Fuller, Justin  
**Subject:** FW: Cause of crack at Crystal River plant not yet known

---

**From:** Ext-Justin.Fuller@stuk.fi [Ext-Justin.Fuller@stuk.fi]  
**Sent:** Tuesday, October 13, 2009 8:30 AM  
**To:** Petteri.Tiippana@stuk.fi  
**Cc:** Lasse.Kuosa@stuk.fi; Jukka.Kallionpaa@stuk.fi  
**Subject:** FW: Cause of crack at Crystal River plant not yet known

Petteri,

I don't know much more about this issue than what the newspaper and NRC posting has in it, but once I become aware of any information that I can share, I will pass it along.

There is a thought that the containment crack was from construction, and I believe that they have a post tensioned containment like OL3. Maybe there will be some lessons learned from the root cause report or NRC inspection report that STUK and/or TVO would like to know.

Regards,

Justin

---

Subject: Cause of crack at Crystal River plant not yet known

This is an article from Ocala.com.

justin thinks you might be interested in this.

Link to the article:  
[www.ocala.com/article/20091010/ARTICLES/910101013](http://www.ocala.com/article/20091010/ARTICLES/910101013)

A-179