

March 16, 2010
UNITED STATES NUCLEAR REGULATORY COMMISSION
REGION IV
611 Ryan Plaza Drive, Suite 400
Arlington, Texas 76011-4005

RECEIVED

MAR 25 2010

DNMS

SUBJECT: Amendment Request
License: 25-21479-01
Docket No. 030-20836

ATTENTION: License Amendment Department


Mattingly Testing Services hereby requests to amend License 25-21479-01 to include the following information;

- 1) Remove field station: 6871 King Avenue West Units A and B, Billings Montana (last month at this location will be April 2010)
- 2) Add field station: 7108 Niehenke Avenue, Billings Montana (We are moving to this field station in April, but the site is available now for inspection)
- 3) Add Danny Schroeder as RSO. Please see attached training information. Danny Schroeder has over 5,000 hours of experience working as a carded Radiographer.

*Reviewer: 1- Request information
on new storage location
IAW N-1556, Vol. 2.
2. Request leak test records.*


Thanks for your help.

Sincerely,



Mark Ficek
President
Mattingly Testing Services, Inc

*RTZ
4-1-2010*



Dayna Thompson
DAYNA THOMPSON
NOTARY PUBLIC for the State of Montana
Residing at Billings, Montana
My Commission Expires Nov. 24, 2012

4 7 2 6 3 5

Danny Schroeder

Has successfully completed the 40 hour technical short course entitled


Radiation Safety Officer

December 7 – December 11, 2009

This certificate presented in La Jolla, California, December 11, 2009

By Nevada Technical Associates, Inc.

Approval codes for C.E. units are: ASRT 30.5 units: NVZ0146001, AAHP 32 units: 2008-00-005, ABIH 4.5 units: 08-1362



Robert Holloway, Ph.D.

Course Coordinator



March 16, 2010

We have the following information documented in our records concerning Daniel Schroeder's NDT experience while employed at Mattingly Testing Services, Inc.

NDT METHOD	TOTAL HOURS
Radiography	7646.25
Ultrasonic Shearwave	0.00
Ultrasonic Thickness	204.00
Magnetic Particle	273.00
Mechanical	0.00
Visual	1047.00
Weld Inspection/CWI	0.00
Thermography	0.00
Non-Chargeable (Training/Admin)	1699.50
TOTAL	10869.75

Experience hours were accumulated between 08/11/05 and 03/15/10.

If you have any questions, please call.

Sincerely,

Dayna Thompson

Torres, RobertoJ

From: Oglesby, John
Sent: Monday, April 05, 2010 7:09 AM
To: Torres, RobertoJ
Cc: Munoz, Rick; Whitten, Jack; Holland, Crystal
Subject: RE: Amendment request from Mattingly Testing

Roberto...I see no conflict with the investigative process regarding their request for change. You might get Rick to weigh in as well. R/John

From: Holland, Crystal
Sent: Thursday, April 01, 2010 4:21 PM
To: Torres, RobertoJ; Oglesby, John
Cc: Munoz, Rick; Whitten, Jack
Subject: RE: Amendment request from Mattingly Testing

Roberto,

As the case agent, John will provide a response to you upon his return to the office... possibly tomorrow.

Take care,

Crystal

From: Torres, RobertoJ
Sent: Thursday, April 01, 2010 3:28 PM
To: Oglesby, John; Holland, Crystal
Cc: Munoz, Rick; Whitten, Jack
Subject: Amendment request from Mattingly Testing

John, Crystal:

Branch B in DNMS has received the attached amendment request from Mattingly Testing to change the radiation safety officer to Danny Schroeder. I recall that there is an ongoing investigation on Mattingly. Before Branch B processes this licensing case (we have not assign it to a reviewer yet) I want to know if this amendment request conflicts with the current investigation or a proposed individual order. Thanks.

Roberto J. Torres
Senior Health Physicist
U.S. Nuclear Regulatory Commission - Region IV
Division of Nuclear Materials Safety
Nuclear Materials Safety Branch B
612 East Lamar Boulevard, Suite 400
Arlington, Texas 76011-4125
Telephone 817-860-8189
Facsimile 817-860-8263
robertoj.torres@nrc.gov

4-06-2010

DATE

This is to acknowledge the receipt of your letter/application dated 3-16-2010, and to inform you that the initial processing, which includes an administrative review, has been performed.

There were no administrative omissions. Your application will be assigned to a technical reviewer. Please note that the technical review may identify other omissions or require additional information.

Please provide to this office within 30 days of your receipt of this card:

The action you requested is normally processed within 90 days.

A copy of your action has been forwarded to our License Fee & Accounts Receivable Branch, who will contact you separately if there is a fee issue involved.

Your action has been assigned Mail Control Number 472635.
When calling to inquire about this action, please refer to this mail control number.
You may call me at 817-860-8103.

Sincerely,

Colleen Murahan

Licensing Assistant

BETWEEN:
License Fee Management Branch, ARM
and
Regional Licensing Sections

: (FOR LFMS USE)
: INFORMATION FROM LTS
: -----
: Program Code: 03320
: Status Code: 0
: Fee Category: 30 EX 2B
: Exp. Date: 20160228
: Fee Comments: _____
: Decom Fin Assur Req'd: N
:

LICENSE FEE TRANSMITTAL

A. REGION

1. APPLICATION ATTACHED
Applicant/Licensee: MATTINGLY TESTING SERVICES, INC.
Received Date: 20100325
Docket No.: 3020836
Control No.: 472635
License No.: 25-21479-01
Action Type: Amendment

2. FEE ATTACHED
Amount: _____
Check No.: /

3. COMMENTS


Signed *Colleen Murnahan*
Date 3-26-2010

B. LICENSE FEE MANAGEMENT BRANCH (Check when milestone 03 is entered /_/)

- 1. Fee Category and Amount: _____
- 2. Correct Fee Paid. Application may be processed for:
Amendment _____
Renewal _____
License _____
- 3. OTHER _____

Signed _____
Date _____

Mattingly Testing Services, Inc
P.O. Box 30316
Billings, MT 59107



United States Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 400
Arlington, TX 76011-4005

7601134005 0024

