Consolidated Edison Company of New York, Inc. 4 Irving Place, New York, N Y 10003
Telephone (212) 460-3819

REGULATORY DOCKET FILE COPY

July 23, 1979

Re: Indian Point Unit No. 2
Docket No. 50-247

Director of Nuclear Reactor Regulation ATIN: Mr. Albert Schwencer, Chief

Operating Reactors Branch No. 1 Division of Operating Reactors

U. S. Nuclear Regulatory Commission Washington, D. C. 20555

Dear Mr. Schwencer:

By letter dated June 29, 1979, Westinghouse WCAP-9600, "Report on Small Break Accidents for Westinghouse NSSS System," was forwarded to Mr. Denwood F. Ross, Jr., Deputy Director of Project Management by the Chairman of the Westinghouse Operating Plants Owners' Group. The purpose of this correspondence is to inform you that the behavior modes and qualitative results illustrated in the report are applicable to Indian Point Unit No. 2. The report also provides generic results that are generally conservative for Indian Point Unit No. 2. Section 6 of that report contains revised Westinghouse emergency operating instructions which are being reviewed for applicability to our facility and subsequent incorporation into our operating procedures as appropriate.

Very truly yours,

William J. Cahill, Jr.

Vice President

A001 10 247 F