JUNE 7 1979

DISTRIBUTION

Docket File 50-247

TERA

J. Buchanan

G. Lainas N. Nerses

Docket No. 50-247

Mr. William J. Cahill, Jr. Vice President
Consolidated Edison Company of New York, Inc.
4 Irving Place
New York, New York, 10003

Dear Mr. Cahill:

NRR Rdg
ORB1 Rdg
A. Schwencer
D. Eisenhut
V. Stello
B. Grimes
R. Vollmer
W. Russell
J. Carter
L. Olshan
C. Parrish
(I&E) 3
OELD

NRC PDR

Local PDR

During our meeting with your staff on March 7-9, 1979 at Indian Point Unit No. 2, we agreed that many valves could be deleted from your inservice testing (IST) program since they performed no safety-related function.

As a result, you submitted, by letter dated April 16, 1979, a list of the valves that you propose be deleted from your IST program. We, along with our consultants from Brookhaven National Laboratory, have reviewed your list. We agreed that most of the valves on this list are not safety-related and can be deleted from your IST program.

There are, however, ten valves on your list that we consider safety-related and they should not be deleted. They are 882, 1810, 894A, 894B, 894C, 894D, 898, MS-52, BFD-77 and BFD-78. This information was discussed with Mr. L. Liberatori of your staff during telephone conversations on May 10 and May 11, 1979.

Furthermore, on May 22, 1979, Mr. Liberatori requested that the following sampling system valves be deleted from the IST program since they're not safety-related: 951, 953, 955A, 955B, 974A, 974B, and 975. We agree that these valves can be deleted from the program.

Sincerely,

Original Signed By

A. Schwencer, Chief Operating Reactors Branch #1 Division of Operating Reactors TUNG

: See next page

DOR:ORB1 DOR:PSB DOR:ORBT DOR:



UNITED STATES NUCLEAR REGULATORY COMMISSION WASHINGTON, D. C. 20555

June 7, 1979

Docket No. 50-247

Mr. William J. Cahill, Jr. Vice President Consolidated Edison Company of New York, Inc. 4 Irving Place New York, New York 10003

Dear Mr. Cahill:

During our meeting with your staff on March 7-9, 1979 at Indian Point Unit No. 2, we agreed that many valves could be deleted from your inservice testing (IST) program since they performed no safety-related function.

As a result, you submitted, by letter dated April 16, 1979, a list of the valves that you propose be deleted from your IST program. We, along with our consultants from Brookhaven National Laboratory, have reviewed your list. We agreed that most of the valves on this list are not safety-related and can be deleted from your IST program.

There are, however, ten valves on your list that we consider safety-related and they should not be deleted. They are 882, 1810, 894A, 894B, 894C, 894D, 898, MS-52, BFD-77 and BFD-78. This information was discussed with Mr. L. Liberatori of your staff during telephone conversations on May 10 and May 11, 1979.

Furthermore, on May 22, 1979, Mr. Liberatori requested that the following sampling system valves be deleted from the IST program since they're not safety-related: 951, 953, 955A, 955B, 974A, 974B, and 975. We agree that these valves can be deleted from the program.

Sincerely

A. Schwencer, Chief

Operating Reactors Branch #1 Division of Operating Reactors

cc: See next page

Mr. William J. Cahill, Jr.
Consolidated Edison Company of New York, Inc. - 2 - June 7, 1979

cc: White Plains Public Library 100 Martine Avenue White Plains, New York 10601

> Joseph D. Block, Esquire Executive Vice President Administrative Consolidated Edison Company of New York, Inc. 4 Irving Place New York, New York 10003

> Edward J. Sack, Esquire
> Law Department
> Consolidated Edison Company
> of New York, Inc.
> 4 Irving Place
> New York, New York 10003

Anthony Z. Roisman Natural Resources Defense Council 917 15th Street, N.W. Washington, D. C. 20005

Dr. Lawrence R. Quarles
Apartment 51
Kendal at Longwood
Kennett Square, Pennsylvania 19348

Theodore A. Rebelowski U. S. Nuclear Regulatory Commission P. O. Box 38 Buchanan, New York 10511