

**SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION**

1. LICENSEE/LOCATION INSPECTED: <i>Beam, Longest and Neff, LLC</i> <i>8126 Castleton Rd</i> <i>Indianapolis, IN 46250</i> REPORT NUMBER(S)                      2010/001	2. NRC/REGIONAL OFFICE  <b>U.S. Nuclear Regulatory Commission</b> <b>Region III</b> <b>2443 Warrenville Road</b> <b>Suite 210</b> <b>Lisle, Illinois 60532-4351</b>
--	---

3. DOCKET NUMBER(S) <i>030-38095</i>	4. LICENSEE NUMBER(S) <i>13-32758-01</i>	5. DATE(S) OF INSPECTION <i>MAY 10, 2010</i>
---	---	---

**LICENSEE:**

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.

\_\_\_\_\_ Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

- 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.  
(Violations and Corrective Actions)

**Licensee's Statement of Corrective Actions for Item 4, above.**

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Edward Kulzer	<i>E. Kulzer</i>	<i>5/10/10</i>

*JKP*

**SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION**

1. LICENSEE Beam, Longest, and Neff, LLC. REPORT NUMBER(S) 2010-001		2. NRC/REGIONAL OFFICE Region III 2443 Warrenville Road, Suite 210 Lisle, IL 60532	
3. DOCKET NUMBER(S) 030-38095	4. LICENSE NUMBER(S) 13-32758-01	5. DATE(S) OF INSPECTION May10, 2010	
6. INSPECTION PROCEDURES USED 87124	7. INSPECTION FOCUS AREAS 03.01-03.07		

**SUPPLEMENTAL INSPECTION INFORMATION**

1. PROGRAM CODE(S) 3121	2. PRIORITY 5	3. LICENSEE CONTACT Jerry Goodwin	4. TELEPHONE NUMBER 317-849-5843
----------------------------	------------------	--------------------------------------	-------------------------------------

Main Office Inspection      Next Inspection Date: May. 2011

Field Office \_\_\_\_\_

Temporary Job Site Inspection \_\_\_\_\_

**PROGRAM SCOPE**

The licensee is a private engineering/consulting company located in Indianapolis, Indiana. They perform soil density in the Indianapolis, Indiana area. The licensee has no gauges.

**Performance Observations**

The licensee had no gauges at the time of this inspection. They are still due for an inspection and should have the gauge next spring.

*JLB*