NRC FORM 591M PART 1 (4-2008)		U.S. NUCLEAR REGULATORY COMMISSION		
10 CFR 2.201	SDECTION DEDODT	AND COMPLIANCE INSPECTION		
SAFETYIN	SPECTION REPORT	AND COMPLIANCE INSPECTION		
LICENSEE/LOCATION INSPECTED:     Panhandle Geotechnical and Environmental, Inc.     818 South Beltline Highway East     Scottsbluff, Nebraska 69361     Location: 809 South 9 <sup>th</sup> Street, Suite B, Douglas, WY		NRC/REGIONAL OFFICE  U.S. Nuclear Regulatory Commission Region IV, 612 East Lamar Blvd, Suite 400 Arlington, Texas 76011-4125		
REPORT NO: 2010-001				
3. DOCKET NUMBER	4. LICENSE NUMBER	5. DATE OF INSPECTION		
030-37783	26-29304-01	April 20, 2010		
LICENSEE: The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:				
X 1. Based on the inspection findings, no violations were identified.				
X 2. Previous violation(s) closed.				
3. The violations(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy to exercise discretion, were satisfied.				
No. 27 (1) (1) (1) (1) (1)		owing requirement(s) and Corrective Action(s):		
4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.				
Licensee's Statement of Corrective Actions for Item 4, above.				
corrective actions is made in accordance with date when full compliance will be achieved)	the requirements of 10 CF	inspector will be taken to correct the violations identified. This statement of FR 2.201 (corrective steps already taken, corrective steps which will be taken, per written response to NRC will be required, unless specifically requested.  Signature Date		
LICENSEE'S REPRESENTATIVE				
	on/Vivian Campbell	hatischar M. Missel April 20, 2010		
NRC FORM 591M PART 1 (Rev. by RIV 3/09) S:\DNMS\\NMB\\BYAKEHYFORM\\S\\Part1 \Publicly\Available.doc				
NRC FORM 591M PART 1 (Rev. by RIV 3/09)  Non-Public Sensitive – S	ecurity-Related	X Public X Non-Sensitive		



## UNITED STATES NUCLEAR REGULATORY COMMISSION

REGION IV 612 EAST LAMAR BLVD, SUITE 400 ARLINGTON, TEXAS 76011-4125

## **DIVISION OF NUCLEAR MATERIALS SAFETY**

DATE / TIME:	=/27/10 4:10 pm	
PRIORITY: IMMEDIATELY 1-HOUR 2-4 HOUR	<u></u>	
MESSAGE TO:	FRANK 24	ong, P.E.
MESSAGE FROM:	Jah schu	Hanson, Luspoctions
NUMBER OF PAGE	s <u>2</u> _PLU	S TRANSMITTAL SHEET
TELECOPY NUMBE	R: (307) 358-8379	VERIFICATION NUMBER: (307) 354-1334
CONTACT:	Latischa Ha	NSON (5) (517) 860 -8286
SPECIAL INSTRUC	TIONS / ATTACHMENTS:	
i) Clear 5"	grinspection Re on today	port, as per duk telephonic
2) Licensin	a contact person	NAME OF THE PARTY
amendm	ent changes cos	To e didenssed for RSO change.
Jack. Wh Roberto. I	iltenan Rc.gov ( orresence gov;	unel fee license ise dideussed for RSO change: (Licensing Chief) Jackie Cookeinreger (Sr. Lic. Person
TRANSMITTED AN	D VERIFIED BY:	DISPOSITION:
		RETURN TO ORIGINATOR:
		PLACE IN MAIL:
NAME	DATE	OTHER: