

	RISK IMPORTANCE		
	LOW	MEDIUM	HIGH
currently operating PWR	everything else	about 80 major components (e.g., AFW pumps)	about 20 major components (e.g., DC batteries, RWST)
AP1000	everything else	about 80 major components (e.g., core make-up tanks)	about 15 major components (e.g., accumulator discharge check valves)
U.S. EPR	everything else	about 70 major components (e.g., medium head safety injection pumps)	about 20 major components (e.g., emergency feedwater storage tanks)