

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: <i>Radiation Therapy Associates, P.C. Harden City, MI</i> REPORT NUMBER(S) <i>2010-001</i>		2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region III 2443 Warrenville Road Suite 210 Lisle, Illinois 60532-4351	
3. DOCKET NUMBER(S) <i>030-53353</i>	4. LICENSEE NUMBER(S) <i>21-26536-01</i>	5. DATE(S) OF INSPECTION <i>June 9, 2010</i>	

LICENSEE:
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

1. Based on the inspection findings, no violations were identified.

2. Previous violation(s) closed.

3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.

_____ Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.
(Violations and Corrective Actions)

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Deborah A. Piskura	<i>Vered Anzenberg</i>	<i>6/9/2010</i>

84

**SAFETY INSPECTION REPORT
AND COMPLIANCE INSPECTION**

1. LICENSEE Radiation Therapy Associates, P.C. REPORT NUMBER(S) 2010-001		2. NRC/REGIONAL OFFICE Region III 2443 Warrenville Road, Suite 210 Lisle, IL 60532	
3. DOCKET NUMBER(S) 030-33353	4. LICENSE NUMBER(S) 21-26536-01	5. DATE(S) OF INSPECTION June 9, 2010	
6. INSPECTION PROCEDURES USED 87131 & 87132	7. INSPECTION FOCUS AREAS 03.01 - 03.08		

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 02200	2. PRIORITY 3	3. LICENSEE CONTACT Ronald C. Lutsic, D.O., RSO	4. TELEPHONE NUMBER 734-522-8540
<input checked="" type="checkbox"/> Main Office Inspection		Next Inspection Date: June 2013	
<input type="checkbox"/> Field Office			
<input checked="" type="checkbox"/> Temporary Job Site Inspection		Dr. Kasmikha, Rochester Hills, MI	

PROGRAM SCOPE

This licensee was a cancer center adjacent to the Garden City Osteopathic Hospital (License No. 21-04072-01) and authorized to use licensed material permitted by Sections 35.300 and 35.400 (1r-192). The licensee occasionally administered I-131 treatments for hyperthyroidism and thyroid cancer (typically one case per year). No beta-emitting radiopharmaceuticals had been used since the previous inspection. The licensee also administered temporary GYM implants using Cs-137 within a Wang applicator; the licensee administered 3 implants since the previous inspection. Licensed activities were conducted by one authorized user/RSO and one medical physicist. All patients who received I-131 therapies were released in accordance with the provisions under Section 35.75. All patients who received Cs-137 implants were hospitalized at the Garden City Osteopathic Hospital. Note that the Cs-137 sources were owned by the hospital who maintained the inventory and leak tests.

This inspection consisted of interviews with licensee personnel, a review of selected records, and a tour of the department.

NOTE TO INSPECTOR: Since the brachytherapy sources are possessed/owned by the Garden City Osteopathic Hospital, and the patients are hospitalized for the implants, the inspection of this licensee as well as the hospital, should be performed concurrently.

Jep