

 Go Back

[Print](#) | [New Search](#) | [Home](#)

## AR 00914559 Report

<b>Aff Fac:</b>	Oyster Creek	<b>AR Type:</b>	CR	<b>Status:</b>	APPROVED
<b>Aff Unit:</b>	NA	<b>Owed To:</b>	A5352CAP	<b>Due Date:</b>	05/31/2009
<b>Aff System:</b>	424			<b>Event Date:</b>	04/19/2009
<b>CR Level/Class:</b>	/			<b>Disc Date:</b>	04/19/2009
<b>How Discovered:</b>	H02			<b>Orig Date:</b>	05/01/2009
<b>WR/PIMS AR:</b>		<b>Component #:</b>	T-11-1		

### Action Request Details

**Subject:** CST TANK ACCESS HATCH TOO SMALL

**Description:** Originator: SAM PRATT Supv Contacted: Vacarro, Makar, Pitt, Cherneski

Condition Description:  
CST Tank hatch is too small and inhibits safe access to tank durring inspection and maint.

Immediate actions taken:  
none

Recommended Actions:  
Install larger hatch; 36" recommended

What activities, processes, or procedures were involved?  
NRC committment; CST Tank inspection using divers

Why did the condition happen?  
Design

What are the consequences?  
Problems entering tank

Were there any adverse physical conditions?  
Difficulty removing diver in emergency

List of knowledgeable individuals:  
Cherneski, Makar, Pitt, Vacarro, Ray, Trombley, Anvari

Repeat or similar condition?  
yes, diver was injured being removed from tank durring prior inspection

Operable Basis:

Reportable Basis:

### Assignments



<b>Assign #:</b>	<u>01</u>	<b>Assigned To:</b>		<b>Status:</b>	AWAIT/C
<b>Aff Fac:</b>	Oyster Creek	<b>Prim Grp:</b>	ACAPALL	<b>Due Date:</b>	05/06/2009
<b>Assign Type:</b>	TRKG	<b>Sec Grp:</b>		<b>Orig Due Date:</b>	MM/MM/YYYY
<b>Priority:</b>					
<b>Schedule Ref:</b>					
<b>Unit Condition:</b>					
<b>Subject/Description:</b>	CST TANK ACCESS HATCH TOO SMALL				