



Kiewit

F A X

Kiewit Pacific Co.

1001 Kamokila Street, Suite 305
Kapolei, HI 96706
808-674-1088 PH
808-674-1233 FAX

To: Anthony Gaines
Fax number: 817-860-8263

From: Jay Stepetin
Fax number: 808-934-4911

Date: 6/22/2010

Regarding:
Request Termination of License 53-29282-01

Phone number for follow-up:
808-469-6786 Cell

Comments:

Please process request for Termination of License

Please Reference the following.....

Docket No. 030-37599

License No. 53-29282-01

Control# 471994

Handwritten initials



Kiewit

Drum Road Upgrade, Phase II
Contract No. W9128-07-C-0013

June 22, 2010

United States
Nuclear Regulatory Commission, Region IV
ATTN: Anthony Gaines
611 Ryan Plaza Drive, Suite 400
Arlington, Texas 76011-4005

SUBJECT: Request Termination of License

Kiewit would like to Request Termination to License No. 53-29282-01 (Amendment 2). All activities associated with transporting, storage and utilization of such materials listed in the license will stop. The sealed sources listed under item 9 of the license have been transferred to Mid Pacific Testing and Inspection Services, Inc. This is effective immediately. Please terminate the license to reflect the subject change. Please find attached the last leak test completed prior to transfer.

Sincerely,

Jay Stepetin
Kiewit Pacific Co.
Contractor Quality Control Systems Manager

Docket: 030-37599
License: 53-29282-01
Control: ~~471994~~

573041

June 3, 2010



Kiewit Pacific Co.
1001 Kamokila Blvd
Kapolei, HI

Attention: Jay Stepetin, RSO

Subject: Nuclear Density Gauge Transfer

Troxler 3440+ ID 60462
CS-137 SN 77-7533, AM-241:BE SN 78-4597

Troxler 3440+ ID 60435
CS-137 SN 77-7526, AM-241:BE SN 47-9529

Dear Mr. Stepetin:

This letter is to confirm the transfer of two Troxler model 3440 nuclear density gauges from your possession to Mid Pacific Testing & Inspection Services, Inc. on the 21st day of May, 2010. Please contact our office at your convenience should you have any questions or require additional information.

Respectfully submitted,
Mid Pacific Testing & Inspection Services, Inc.

James Merriman, PE
Director of Testing, RSO

**Troxler Electronic Laboratories, Inc.**

3008 Cornwallis Rd., P.O. Box 12057

Research Triangle Park, NC 27709

Tel: (877) 876-9537 Fax: (866) 391-2759

License: NC 032-0182-1

Jay Stepetin
Kiewit Pacific Co.
1001 Kamokila Blvd.
Suite 305
Kapolei, HI 96707

Cust ID: 11033

LEAK TEST CERTIFICATE

DEVICE:

Model: 3440P Serial No: 60435

SEALED SOURCES:

Serial No.	Measure Date	Nuclide	GBq	mCi
77-7526	10/23/2007	CS-137	0.296	8
47-9529	08/22/1986	AM-241:BE	1.48	40

LEAK TEST ANALYSIS:

Sample collected on: 01/13/2010
 Sample analyzed on: 01/20/2010 at 3:45:00 PM
 Analyzed by: S.Browne

	ALPHA	BETA-GAMMA
Conversion factor (cpm/Bq)	1.13E+01	1.93E+01
Background measurement (cpm)	1	24
Sample measurement (cpm)	0	16
Activity (Bq)	< MDA	< MDA
Min. Detectable Activity (Bq)	6.1E-01	1.3E+00

This certifies that the leak test results are:

Less than 185 Bq (0.005 uCi) Greater than 185 Bq (0.005 uCi)

**Troxler Electronic Laboratories, Inc.**

3008 Cornwallis Rd., P.O. Box 12057

Research Triangle Park, NC 27709

Tel: (877) 876-9537 Fax: (866) 391-2759

License: NC 032-0182-1

Jay Stepetin
Kiewit Pacific Co.
1001 Kamokila Blvd.
Suite 305
Kapolei, HI 96707

Cust ID: 11033

LEAK TEST CERTIFICATE

DEVICE:

Model: 3440P **Serial No:** 60462

SEALED SOURCES:

Serial No.	Measure Date	Nuclide	GBq	mCi
77-7533	10/23/2007	CS-137	0.296	8
78-4597	09/17/2007	AM-241:BE	1.48	40

LEAK TEST ANALYSIS:

Sample collected on: 01/13/2010
Sample analyzed on: 01/20/2010 at 3:44:00 PM
Analyzed by: S.Browne

	ALPHA	BETA-GAMMA
Conversion factor (cpm/Bq)	1.13E+01	1.93E+01
Background measurement (cpm)	1	24
Sample measurement (cpm)	0	23
Activity (Bq)	< MDA	< MDA
Min. Detectable Activity (Bq)	6.1E-01	1.3E+00

This certifies that the leak test results are:

Less than 185 Bq (0.005 uCi) **Greater than 185 Bq (0.005 uCi)**

7-13-2010
DATE

This is to acknowledge the receipt of your letter/application dated 6-22-10, and to inform you that the initial processing, which includes an administrative review, has been performed.

There were no administrative omissions. Your application will be assigned to a technical reviewer. Please note that the technical review may identify other omissions or require additional information.

Please provide to this office within 30 days of your receipt of this card:

The action you requested is normally processed within 90 days.

A copy of your action has been forwarded to our License Fee & Accounts Receivable Branch, who will contact you separately if there is a fee issue involved.

Your action has been assigned **Mail Control Number** 573041.
When calling to inquire about this action, please refer to this mail control number.
You may call me at 817-860-8103.

Sincerely,

Licensing Assistant

BETWEEN:

Accounts Receivable/Payable
and
Regional Licensing Branches

[FOR ARPB USE]
INFORMATION FROM LTS

Program Code: 03121
Status Code: Pending Termination
Fee Category: 3P
Exp. Date:
Fee Comments:
Decom Fin Assur Reqd: N

License Fee Worksheet - License Fee Transmittal

A. REGION

1. APPLICATION ATTACHED

Applicant/Licensee: KIEWIT PACIFIC CO
Received Date: 06/25/2010
Docket Number: 3037599
Mail Control Number: 573041
License Number: 53-29282-01
Action Type: Termination

2. FEE ATTACHED

Amount: _____

Check No.: _____

3. COMMENTS

Signed: Colleen Murnahan

Date: 6-25-2010

B. LICENSE FEE MANAGEMENT BRANCH (Check when milestone 03 is entered / /)

1. Fee Category and Amount: _____

2. Correct Fee Paid. Application may be processed for:

Amendment: _____

Renewal: _____

License: _____

3. OTHER _____

Signed: _____

Date: _____

Murnahan, Colleen

From: Cook, Jackie
Sent: Friday, July 02, 2010 1:45 PM
To: Murnahan, Colleen
Subject: FW: Kiewit Contact Info

Colleen:

Please update LTS 2.0 with the contact information for the RSO listed below. I tried to do it but I didn't want to mess up anything by assigning me as the system administrator.

Thanks,

Jackie

From: Gaines, Anthony
Sent: Thursday, June 17, 2010 3:10 PM
To: Cook, Jackie
Subject: Kiewit Contact Info

Jackie,

Here is the Kiewit contact info I got from the District Manager for William Whitaker the RSO –

Cell number – 615-517-0168
Office number – 719-393-0026

Email – Bill.Whitaker@kiewit.com

Colorado Springs Fax where Bill is – 719-393-7418
Littleton Fax where Manager is – 303-932-8533

Tony

*Done
CW
7-2-10*