

Rafael Flores Senior Vice President & Chief Nuclear Officer rafael.flores@iuminant.com Luminant Power P O Box 1002 6322 North FM 56 Glen Rose, TX 76043

T 254.897.5590 F 254.897.6652 C 817.559.0403

Ref. # 10 CFR 52

CP-201001052 Log # TXNB-10056

August 9, 2010

U. S. Nuclear Regulatory Commission Document Control Desk Washington, DC 20555 ATTN: David B. Matthews, Director Division of New Reactor Licensing

SUBJECT: COMANCHE PEAK NUCLEAR POWER PLANT, UNITS 3 AND 4 DOCKET NUMBERS 52-034 AND 52-035 RESPONSE TO REQUEST FOR ADDITIONAL INFORMATION NO. 4846

Dear Sir:

Luminant Generation Company LLC (Luminant) submits herein the response to Request for Additional Information (RAI) No. 4846 for the Combined License Application for Comanche Peak Nuclear Power Plant Units 3 and 4. The RAI involves the turbine inspection procedure.

Should you have any questions regarding this response, please contact Don Woodlan (254-897-6887, Donald.Woodlan@luminant.com) or me.

There are no commitments in this letter.

I state under penalty of perjury that the foregoing is true and correct.

Executed on August 9, 2010.

Sincerely,

Luminant Generation Company LLC

Rafael Flores

Attachment:

Response to Request for Additional Information No. 4846 (CP RAI #169)

U. S. Nuclear Regulatory Commission CP-201001052 TXNB-10056 8/9/2010 Page 2 of 2

Electronic distribution w/attachment:

Rafael.Flores@luminant.com mlucas3@luminant.com jeff.simmons@energyfutureholdings.com Bill.Moore@luminant.com Brock.Degeyter@energyfutureholdings.com rbird1@luminant.com Matthew.Weeks@luminant.com Allan.Koenig@luminant.com Timothy.Clouser@luminant.com Ronald.Carver@luminant.com David.Volkening@luminant.com Bruce.Turner@luminant.com Eric.Evans@luminant.com Robert.Reible@luminant.com donald.woodlan@luminant.com John.Conly@luminant.com JCaldwell@luminant.com David.Beshear@txu.com Ashley.Monts@luminant.com Fred.Madden@luminant.com Dennis.Buschbaum@luminant.com Carolyn.Cosentino@luminant.com NuBuild Licensing files

Luminant Records Management (.pdf files only)

shinji_kawanago@mnes-us.com masanori_onozuka@mnes-us.com ck_paulson@mnes-us.com joseph_tapia@mnes-us.com russell_bywater@mnes-us.com diane_yeager@mnes-us.com mutsumi_ishida@mnes-us.com nan_sirirat@mnes-us.com nicolas_kellenberger@mnes-us.com rjb@nei.org kak@nei.org michael.takacs@nrc.gov cp34update@certrec.com michael.johnson@nrc.gov David.Matthews@nrc.gov Balwant.Singal@nrc.gov Hossein.Hamzehee@nrc.gov Stephen.Monarque@nrc.gov jeff.ciocco@nrc.gov michael.willingham@nrc.gov john.kramer@nrc.gov Brian.Tindell@nrc.gov Alicia.Williamson@nrc.gov Elmo.Collins@nrc.gov Loren.Plisco@nrc.com Laura.Goldin@nrc.gov James.Biggins@nrc.gov Susan.Vrahoretis@nrc.gov ComanchePeakCOL.Resource@nrc.gov sfrantz@morganlewis.com jrund@morganlewis.com tmatthews@morganlewis.com regina.borsh@dom.com diane.aitken@dom.com

\$

RESPONSE TO REQUEST FOR ADDITIONAL INFORMATION

Comanche Peak, Units 3 and 4

Luminant Generation Company LLC

Docket Nos. 52-034 and 52-035

RAI NO.: 4846 (CP RAI #169)

SRP SECTION: 10.02.03 - Turbine Rotor Integrity

QUESTIONS for Component Integrity, Performance, and Testing Branch 1 (AP1000/EPR Projects) (CIB1)

DATE OF RAI ISSUE: 7/8/2010

QUESTION NO.: 10.02.03-2

Revision 1 of the Comanche Peak COL FSAR revised Section 10.2.3.5 to state that a turbine maintenance and inservice inspection procedure will be established prior to fuel load. However, the description of the inspection program, including the inspection intervals were not provided in this revised COL FSAR Section 10.2.3.5, as requested in the NRC staff's RAI Number 6 (2614). Therefore, Luminant is requested to provide the following information in order to meet the requirements of General Design Criterion 4 of 10 CFR Part 50:

- a) The guidelines in Section C.I.10.2.3.5 of Part I to Regulatory Guide (RG) 1.206 specify that if the plant-specific inspection program is not available at the time of the COL application, the representative information (description of the inspection program and inspection interval) may be submitted for staff review as part of the COL application. Therefore, describe the inservice inspection program and inspection intervals in the COL FSAR, or specify in the COL FSAR that the inspection procedure will be consistent with the inspection program and inspection intervals identified in Section 10.2.3.5 of the US-APWR DCD FSAR.
- b) The submittal and implementation of the inservice inspection procedure should be included as a proposed license condition in Section 3 to Part 10 of the Comanche Peak COL application since this item will not be resolved prior to the issuance of the license. The proposal of a license condition, as discussed in Section C.I.10.2.3.5 of Part I to RG 1.206, ensures that the as-built plant is consistent with the design reviewed during the licensing process.

1

ANSWER:

 a) FSAR Section 10.2 incorporated by reference DCD Tier 2 Section 10.2, which includes a full description of the turbine inspection program. By incorporating this information from the DCD, the FSAR establishes that the inspection procedure will be consistent with the DCD inspection program and inspection interval. FSAR Subsection 10.2.3.5 supplemented the DCD to address COL Item U. S. Nuclear Regulatory Commission CP-201001052 TXNB-10056 8/9/2010 Attachment Page 2 of 5

10.2(1) by adding a statement that the turbine maintenance and inspection procedure will be established prior to fuel load.

The COLA FSAR has been revised to clarify that the procedure will be consistent with the maintenance and inspection program plan activities and inspection intervals identified in DCD Subsection 10.2.3.5.

b) The turbine inspection program has been added to a license condition in Subsection 3 Specific Proposed License Conditions, Part 10 of the COLA.

Impact on R-COLA

See attached marked-up FSAR Revision 1 page 10.2-1 and Part 10 Revision 1 pages 3, 4 and 6.

Я

Impact on DCD

None.

Comanche Peak Nuclear Power Plant, Units 3 & 4 COL Application Part 2, FSAR

10.2 TURBINE-GENERATOR (T/G)

This section of the referenced DCD is incorporated by reference with the following departures and/or supplements.

10.2.3.5 Inservice Inspection

STD COL 10.2(1) Replace the last paragraph of DCD Subsection 10.2.3.5 with the following.

A turbine maintenance and inspection procedure will be established prior to fuel load. The procedure will be consistent with the maintenance and inspection program plan activities and inspection intervals identified in DCD Subsection 10.2.3.5.

RCOL2_10.0 2.03-2

10.2.5 Combined License Information

Replace the content of DCD Subsection 10.2.5 with the following.

STD COL 10.2(1) COL 10.2(1) Inservice Inspection

This Combined License (COL) item is addressed in Subsection 10.2.3.5.

Comanche Peak Nuclear Power Plant, Units 3 & 4 COL Application Part 10 - ITAAC and Proposed License Conditions

2.3 Operational Programs

Operational Programs are identified in <u>FSAR</u> Table 13.4-201 and theirand <u>Subsection 10.2.3.5. Their</u> implementation by the milestones indicated in the <u>Table isbelow represents</u> a potential condition to the license. Some of these programs may be adequately controlled by other methods such as the regulations, the technical specifications or a commitment tracking system and will not need to be addressed inas a license condition. A proposed Proposed license conditions isare provided in sectionSection 3 below based upon the current information in Chapter 13 of the COLA-FSAR.

2.4 Environmental Protection Plan

The Environmental Protection Plan (EPP) and its implementation may also be a potential condition to the license. The EPP has typically been an appendix to the operating license and that precedent may be followed for COLs as well. No plant specific environmental items have been identified which are not adequately controlled by regulations, the appropriate permits, etc. and thus an EPP has not been proposed and is not needed.

2.5 Technical Specifications

Implementation of Technical Specifications prior to fuel load could also constitute a potential condition to the license. The Technical Specifications have typically been an appendix to the operating license and that precedent may be followed for COLs as well.

2.6 Emergency Planning Actions

Execution of Letters of Agreement with State and local entities identifying the specific nature of arrangements in support of emergency preparedness and certifying the agency's concurrence with the emergency action levels prior to the full-participation exercise is a potential condition to the license. A proposed license condition is provided in section 3 below.

Submittal of a fully developed set of site-specific Emergency Action Levels (EALs) to the NRC in accordance with NEI 99-01, Revision 5 at least 180 days prior to initial fuel load is a potential condition to the license. A proposed license condition is provided in section 3 below.

2.7 Others

The current operating licenses have some typical license conditions in areas such as security, fire protection and others. These current license conditions may or may not apply to COLs.

3. Specific Proposed License Conditions

The license conditions identified thus far during the COL development and review. are:

RCOL2_10.0 2.03-2

RCOL2_13.0

RCOL2 13.0

3-2

3-8

3

Revision 1

Comanche Peak Nuclear Power Plant, Units 3 & 4 COL Application Part 10 - ITAAC and Proposed License Conditions

.

Proposed License Condition	Source	
The plant-specific PTS evaluation of the as-procured reactor vessel material properties will be submitted to the NRC within 12 months following acceptance of the reactor vessel.	Answer to RAI 2353 (CP RAI #8) question 05.03.02-3 as provided in TXNB-09028 dated August 7, 2009.	
The licensee shall implement the programs or portions of programs identified in the table below on or before the associated milestones.	COLA FSAR Table 13.4-201 Items 3, 5, 6, 8, 9, 10, 12, 15, 18, and 19.	
	COLA FSAR Subsection 10.2.3.5	RCOL2_10.0 2.03-2
 <u>A. Prior to the full-participation exercise to be conducted</u> in accordance with the requirements of Appendix E to 10 <u>CFR Part 50</u>, Luminant shall establish Letters of Agreement with the following entities: <u>a. Governors Division of Emergency Management</u> (GDEM), Texas Department of Public Safety 	Answer to RAI 3295 (CP RAI #70) question 13.03-1 and RAI 3327 (CP RAI #78) questions 13.03-2 and 13.03-8.	RCOL2_13.0 3-1 RCOL2_13.0 3-2 RCOL2_13.0 3-8
b. Texas Department of State Health Services		
c. Hood County Judge		
d. Somervell County Judge		
These Letters of Agreement will identify the specific nature of arrangements in support of emergency preparedness for operation of the proposed new nuclear units and certify the agency's concurrence with the emergency action levels described in Comanche Peak Units 3 & 4 Combined License Application Emergency Plan Procedure, "Assessment of Emergency Action Levels, Emergency Classification and Plan Activation."		
B. The licensee shall complete development of the site-specific Emergency Action Levels (EALs) presented in Appendix 1 to the Comanche Peak Nuclear Power Plant Units 3 & 4 Combined License Application Emergency Plan in accordance with NEI 99-01, Revision 5, with few differences or deviations. The fully developed site-specific EAL scheme shall be submitted to the NRC for confirmation at least 180 days prior to initial fuel load.	/	RCOL2_13.0 3-1 S01

Operational Programs to be implemented per License Condition above:

Program Title	Milestone
Environmental Qualification Program	Prior to Initial Fuel Load

Revision 1

Comanche Peak Nuclear Power Plant, Units 3 & 4 COL Application Part 10 - ITAAC and Proposed License Conditions

Program Title	Milestone	
FFD Program for persons required to physically report to the TSC or EOF	Prior to the conduct of the first full-participation emergency preparedness under 10 CFR 50, App E, Section F.2.a	
FFD Program for Operation	Prior to the earlier of: Licensee's receipt of fuel assemblies onsite or	NONE-3
	Establishment of a protected area or The 10 CFR 52.103(g) finding	
Turbine inspection program	Prior to fuel load	RCOL2_10.0