

## **PUBLIC SUBMISSION**

As of: August 17, 2010 Received: August 12, 2010 Status: Pending\_Post Tracking No. 80b2f439

Comments Due: August 13, 2010

Submission Type: Web

Docket: NRC-2010-0202

Draft Regulatory Guide: Issuance, Availability

Comment On: NRC-2010-0202-0001

Draft Regulatory Guide: Issuance, Availability

**Document:** NRC-2010-0202-DRAFT-0004 Comment on FR Doc # 2010-14339 RULES AND DIRECTIVES
BRANCH
USARC

JUNE 17 AN III: 3)

## **Submitter Information**

Name: Gregory Wilkosz

Address:

15 Thames St. Groton, CT, 06340

Organization: Zachry Nuclear Engineering, Inc.

## **General Comment**

I would like to submit the following comment on Draft Regulatory Guide DG-1240, "Condition Monitoring Program for Electric Cables Used In Nuclear Plants":

Page 5 of DG-1240 -- Another disadvantage for the use of an illuminated borescope is that it may be considered a "pull-by" and not be allowed at many plants. For plants that allow "pull-bys", it is typically required that the cables in the conduit in which the "pull-by" occurred are functionally tested after the "pull-by". If the cable is baked into the conduit, which is typical for heater bay and steam tunnel cables, for example, the inspection could damage the cable.

SOUSI Review Complete Themplite = ADM-013

ERDS=ADM-03 Old=RA-Jervey(195) M. Case (msc)