

6/15/2010
#5 FR 33853

3

PUBLIC SUBMISSION

As of: August 17, 2010
Received: August 12, 2010
Status: Pending_Post
Tracking No. 80b2f439
Comments Due: August 13, 2010
Submission Type: Web

Docket: NRC-2010-0202
Draft Regulatory Guide: Issuance, Availability

Comment On: NRC-2010-0202-0001
Draft Regulatory Guide: Issuance, Availability

Document: NRC-2010-0202-DRAFT-0004
Comment on FR Doc # 2010-14339

RECEIVED

2010 AUG 17 AM 11:37

RULES AND DIRECTIVES
BRANCH
USNRC

Submitter Information

Name: Gregory Wilkosz
Address:
15 Thames St.
Groton, CT, 06340
Organization: Zachry Nuclear Engineering, Inc.

General Comment

I would like to submit the following comment on Draft Regulatory Guide DG-1240, "Condition Monitoring Program for Electric Cables Used In Nuclear Plants":

Page 5 of DG-1240 -- Another disadvantage for the use of an illuminated borescope is that it may be considered a "pull-by" and not be allowed at many plants. For plants that allow "pull-bys", it is typically required that the cables in the conduit in which the "pull-by" occurred are functionally tested after the "pull-by". If the cable is baked into the conduit, which is typical for heater bay and steam tunnel cables, for example, the inspection could damage the cable.

*SOUSI Review Complete
Template = ADM-013*

*E-REDS = ADM-013
Add = R.A-Jervey (raj)
M. Case (mjc)*