



Weatherford®

August 11, 2010

RECEIVED

AUG 12 2010

DNMS

U.S. NRC Region IV
611 Ryan Plaza, Suite 400
Arlington, TX 76011-4005

Sent VIA FedEx tracking number: 4119 2723 4459

Re: License – 42-26891-01, Amendment Request to add model AM1.G10

To Whom It May Concern:

Weatherford requests an amendment to the 42-26891-01 license to add the following source model in the form and activity listed below. This source is an energy compensation source housed within logging tools used in oil and gas well logging.

Add

- | | |
|-------------------|---|
| 1. Manufacturer: | Eckert & Ziegler |
| Model: | AM1.G10 |
| Isotope: | Am-241 |
| Maximum Activity: | Not to exceed 10 uCi each |
| Authorized Use: | Energy Compensation Source housed in logging tools used for oil & gas well logging. |

If you have any questions related to this matter, please do not hesitate to contact me. My direct contact information is shown below.

Respectfully,

Christopher "Sean" Perry
US Radiation Safety Officer

Weatherford International, Inc.
7504 Benbrook Parkway
Benbrook, TX 76126
Telephone: 817.249.7822
Facsimile: 972.692.6016

johnathan.poe@weatherford.com

Na 573327

8-18-2010

DATE

This is to acknowledge the receipt of your letter/application dated
8-11-2010, and to inform you that the initial processing,
which includes an administrative review, has been performed.

☒ There were no administrative omissions. Your application will be assigned to a technical reviewer. Please note that the technical review may identify other omissions or require additional information.

☐ Please provide to this office within 30 days of your receipt of this card:

The action you requested is normally processed within 90 days.

☐ A copy of your action has been forwarded to our License Fee & Accounts Receivable Branch, who will contact you separately if there is a fee issue involved.

Your action has been assigned **Mail Control Number** 523327.
When calling to inquire about this action, please refer to this mail control number.
You may call me at 817-860-8103.

Sincerely,

Colleen Murnahan

Licensing Assistant

BETWEEN:

Accounts Receivable/Payable
and
Regional Licensing Branches

[FOR ARPB USE]
INFORMATION FROM LTS

Program Code: 03110
Status Code: Pending Amendment
Fee Category: 5A
Exp. Date:
Fee Comments:
Decom Fin Assur Req'd: Y

License Fee Worksheet - License Fee Transmittal

A. REGION

1. APPLICATION ATTACHED

Applicant/Licensee: WEATHERFORD INTERNATIONAL INC
Received Date: 08/16/2010
Docket Number: 3030118
Mail Control Number: 573327
License Number: 42-26891-01
Action Type: Amendment

2. FEE ATTACHED

Amount: _____

Check No.: _____

3. COMMENTS

Signed: _____

Colleen Murnahan

Date: _____

8-16-2010

B. LICENSE FEE MANAGEMENT BRANCH (Check when milestone 03 is entered / /)

1. Fee Category and Amount: _____

2. Correct Fee Paid. Application may be processed for:

Amendment: _____

Renewal: _____

License: _____

3. OTHER _____

Signed: _____

Date: _____

ORIGIN ID: FTWA (817) 249-7013
CHRISTOPHER SEAN PERRY
WEATHERFORD INTERNATIONAL, INC.
7504 BENBROOK PKWY

BENBROOK, TX 76126
UNITED STATES US

SHIP DATE: 11AUG10
ACTWGT: 0.5 LB MAN
CAD: 558726/CAFE2450

BILL SENDER

TO U.S. NRC REGION IV

611 RYAN PLAZA
SUITE 400
ARLINGTON TX 76011

REF: 87721

DEPT: RAM & EXP COMPLIANCE



FedEx
Express



00920091130/222

THU - 12AUG A1


TRK#
0201

4119 2723 4459 STANDARD OVERNIGHT

AD FWHA

76011

TX-US
DFW



Vol.

Envelope