



DECAY HEAT PUMP AND MOTOR BEARING OIL DRAIN AND WINDING TEMPERATURE INSTRUMENTATION			
P42-2	T	FUNCTION	
TE (3)	T (4)		
DH50A1	375	PUMP BEARING OT.	
DH50A2	371	PUMP BEARING-MOTOR END OT.	
DH51A1	373	MOTOR BEARING-PUMP END OT.	
DH51A2	372	MOTOR BEARING OT.	
DH52A1		MOTOR STATOR	
DH52A2		MOTOR STATOR	
DH52A3		MOTOR STATOR	
DH52A4		MOTOR STATOR	
DH52A5		MOTOR STATOR	
DH52A6	374	MOTOR STATOR	

NOTES:
1. FOR NOTES SEE DRAWING M-033A.

LR NOTES:
A. FOR GENERAL LICENSE RENEWAL NOTES REFER TO LR-M001-01.

LICENSE RENEWAL BOUNDARY DRAWING
LR-M033C REV. 0

- SYSTEMS SHOWN ON THIS DRAWING:
- 08: DECAY HEAT REMOVAL & LOW PRESSURE INJECTION
- 10: MAKEUP & PURIFICATION
- 15: SPENT FUEL POOL COOLING & CLEANUP
- 19: REACTOR COOLANT VENT & DRAIN
- 20: STATION PLUMBING, DRAINS, & SUMPS
- 25: BORON RECOVERY

BECHTEL ASSOCIATES
PROFESSIONAL CORPORATION (OHIO)
GAITHERSBURG, MARYLAND
DAVIS-BESSE NUCLEAR POWER STATION
UNIT NO. 1
THE TOLEDO EDISON COMPANY
PIPING & INSTRUMENT DIAGRAM
DECAY HEAT TRAIN 2

JOB NO.	DRAWING NO.	REV.
12501	M-033C	24

THIS DRAWING REV. 0 SUPERSEDES IN PART DRAWING M-033 REV. 51. WORK THIS DRAWING WITH M-033A AND M-033B.

D-51 01251