## EVENT CLASS: LAS - LOST, ABANDONED, STOLEN MATERIAL

## LICENSEE / REPORTING PARTY INFORMATION:

Licensee/Reporting party name:	Baker Hughes			
License number :	17-27437-01			
Docket number :	030-32818			
Licensee's City of record :	Broussard			
Licensees State of record :	Louisiana			
NRC regulated?	yes	If so, what Region?	IV	
Working under reciprocity?	no			

## **EVENT INFORMATION:**

In what City and State did the event occur?	Offshore Federal waters	
Event date :	7/29/2010	
Discovery date :	7/29/2010	
Report date :	8/4/2010 with written report submitted 9/1/2010	
Agreement State reportable?	no	
NRC reportable?	yes	
Reporting regulation :	10 CFR 39.77(d)	
NMED Item Number :	ML 102500153 not in NMED as of 9/7/10	

## ADDITIONAL PARTIES INVOLVED:

Name :	Apache Corporation	
License number :	N/A	
City:		
State :		

## LICENSEE EVENT REPORT EVALUATION FORM Page 2 of 3

# EVENT CLASS: LAS - LOST, ABANDONED, STOLEN MATERIAL

# CONSULTANT INFORMATION (if any):

Consultant name :	None
Company :	
Who hired consultant?	

## **DEVICE INFORMATION:**

Manufacturer :	Logging tool
Model number :	N/A
Serial number :	N/A

## RADIATION SOURCE INFORMATION:

Isotope :	Americium/Beryllium-241	Cesium-137
Activity:	5 Curies	2.5 curies
Manufacturer :	QSA Global	QSA Global
Model number :	AMN.CY3	CDC.CY4
Serial number :	SS44834B	PP24468B

#### LICENSEE EVENT REPORT EVALUATION FORM

Page 3 of 3

## EVENT CLASS: LAS - LOST, ABANDONED, STOLEN MATERIAL

#### NARRATIVE EVENT DESCRIPTION:

A logging tool became stuck while logging a well in the Gulf of Mexico at OCS-G 05800 A005 ST01BP00 Ewing Banks Block 826. The tool held 2 radioactive sources, as described above. The sources were declared irretrievable, and permission to abandon the source in the well was given by NRC. For more information see ADAMS ML 102500153

#### **CORRECTIVE ACTIONS:**

A cement plug was set over the sources, with the top of cement plug at a depth of 14,440 feet. A copy of the abandonment report was placed in the well file, as well as abandonment plaque.

#### RECOMMENDED FOLLOWUP:

Was a reactive inspection conducted?	no	If so, inspection report number :	N/A
Is LER recommended for closure?	yes		
Is this NMED Item Number recommended to reflect "complete"?	yes		

LER Evaluator:  Name: Martin Date: 9/8/10	Branch Chief or Designee Review:  Name: Date: 9 18 18010
11011	70/1/0
	1////