Cardiac Care Consultants, P.C. 1730 45th Street Munster, Indiana 46321

June 10, 2010

James Mullauer
U.S. Nuclear Regulatory Commission
Region III
NRC Materials Licensing Branch
2443 Warrenville Road, Suite 210
Lisle, IL 60532-4351

Re: License #13-32585-01

Dear Mr. Mullauer:

We have now completed our move from 9116 and 9124 Columbia Ave. to our new facility at 1730 45th Street, Munster IN. All radioactive material was transferred to the new site and a closeout survey was completed of the previous use and storage-location at 9124 Columbia Ave. to ensure there is no contamination or radioactive materials remaining. A copy of the closeout survey is attached.

Our mailing address should be changed to the 1730 45th Street location.

Please contact us if additional information is needed.

Thank you.

Sincerely,


Shashi Divakaruni, M.D., Owner

Nuclear Medicine

Date: June 7, 2010 Location: Cardiac Care Consultants, 9124 Columbia Ave. Munster, IN					
Instruments used: Survey Meter <u>Ludlum, 2241-2 with thin</u> window g.m. probe # 217849			Well Counter #13228		
Calibrated: August 27, 2009			Efficiency=	82 %	
Survey Performed by: Stan Buhr			Bgnd = .03 mr/hr, 162 cpm		
Number Location (see sketch 1 - 4 = hot lab area	h) mr/hr	_dpm/100cm ²		. 1	
1 Counter top	03	0			
2 Counter top	.03	10			<u>12</u>
2 Jasida achinata	02	22	Floor		L 4
3 Inside cabinets	.03	23	Floor	03	0
4 Inside cabinets	03		Floor	.03 _	0
5 - 7 = Storage Room 5 Floor	.03	<u>24</u> _ 11	Floor	.03	
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	,00	25	Floor	.03	11
6 Floor	03	8_ 2	6 - 35 = treadmill room		
		<u> 26</u>	Floor	.03	11
7 Floor	03	5		00	
8 - 25 = camera room 8 Floor	03	27	Floor	.03	. 8
0 F1001	03	028	Floor	.03	0_
9 Floor		0	3 1001		
		29	Floor	.03	0'
10 Floor	03	7			
		<u>30</u> _	Floor		16
11 Floor	.03	11			
12) Floor	02	31_	Floor	03	6
12 Floor	03	<u>12</u> 	Floor	.03	. 0
13 Floor	03 _	0	1-1001		
		33	Floor	03	0
14 Floor	03	9			
		34	Floor	03	0
15 Floor	03	0			
4C Flore	00	35_	Floor	.03	13
16 Floor	03_		40 = exam room injec		
17 Floor	03_	<u>36</u> _	Floor	03	0
17 1 100;		<u>14</u> 37	Floor	.03	7_
18 Floor	03	6			
,		38	Floor	03	18
19 Floor	03	7			
20 Fl-27	5.0	<u>39</u>	Floor	03	0
20 Floor	03	040	Elear	00	40
		<u>40</u>	Floor	03	10

CARDIAC CARE COSULTANTS NEW OFFICE 9124 COLUMBIA AVE MUNSTER, IN 46321

OUTSIDE WALL



OUTSIDE WALL

CARDIAC CARE CONSULTANTS, P.C. 1730 45th Street Munster, Indiana 46321

U.S. Nuclear Regulatory Commission Region III Materials Licensing Branch 2443 Warrenville Road, Suite210 Lisle, Il 60532-4351

Re: License # 13-32585-01

Me Drichami

We have submitted an Addendum to our license for the removal of Dr. Griep from our license, a follow up will be forwarded by our physicist. Also forwarding a copy of the closing survey done at our previous facility at 9124 Columbia Ave.

Please feel free to contact us if additional information is needed.

Thank you.

Sincerely,

Anuradha Divakaruni M..D., Radiation Safety Officer.